

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

NTUC INCOME INSURANCE CO-OPERATIVE LTD	y3m4		
#05-01 NTUC TRADE UNION HOUSESINGAPORE 189556 ATTN: DIANA TAY  Code: INC  1. Policy Particulars:- THIRD PARTY CLAIM  Insured Veh. SKE 6151B  Veh. Inspected GY 270Y  Policy No. Coverage (\$) 0.00  Claim No. MT/1182056-002 Excess (\$) 0.00  Assign From DIANA TAY  Assign Date 02/08/2022  2. Vehicle Particulars & Condition  Make & Model NISSAN NV350 (M) c.c 2488  Engine No. HIDDEN Year of Reg. 2017  Chassis No. JN1MC2E26Z0008466 Colour SILVER  Odometer 148044 KM Steering IN ORDER  Brakes IN ORDER Modification NIL  General GOOD  3. Conditions of Tyres			
1. Policy Particulars:- THIRD PARTY CLAIM  Insured Veh. SKE 6151B Veh. Inspected GY 270Y  Policy No. Coverage (\$) 0.00  Claim No. MT/1182056-002 Excess (\$) 0.00  Assign From DIANA TAY Assign Date 02/08/2022  2. Vehicle Particulars & Condition  Make & Model NISSAN NV350 (M) c.c 2488  Engine No. HIDDEN Year of Reg. 2017  Chassis No. JN1MC2E26Z0008466 Colour SILVER  Odometer 148044 KM Steering IN ORDER  Brakes IN ORDER Modification NIL  General GOOD  3. Conditions of Tyres			
Insured Veh.   SKE 6151B   Veh. Inspected   GY 270Y			
Policy No.   Coverage (\$)   0.00			
Claim No.         MT/1182056-002         Excess (\$)         0.00           Assign From         DIANA TAY         Assign Date         02/08/2022           Vehicle Particulars & Condition           Make & Model         NISSAN NV350 (M)         c.c         2488           Engine No.         HIDDEN         Year of Reg.         2017           Chassis No.         JN1MC2E26Z0008466         Colour         SILVER           Odometer         148044 KM         Steering         IN ORDER           Brakes         IN ORDER         Modification         NIL           General         GOOD         Conditions of Tyres			
Assign From DIANA TAY Assign Date 02/08/2022  2. Vehicle Particulars & Condition  Make & Model NISSAN NV350 (M) c.c 2488  Engine No. HIDDEN Year of Reg. 2017  Chassis No. JN1MC2E26Z0008466 Colour SILVER  Odometer 148044 KM Steering IN ORDER  Brakes IN ORDER Modification NIL  General GOOD  Conditions of Tyres			
2. Vehicle Particulars & Condition  Make & Model NISSAN NV350 (M) c.c 2488  Engine No. HIDDEN Year of Reg. 2017  Chassis No. JN1MC2E26Z0008466 Colour SILVER  Odometer 148044 KM Steering IN ORDER  Brakes IN ORDER Modification NIL  General GOOD  3. Conditions of Tyres			
Make & Model NISSAN NV350 (M) c.c 2488  Engine No. HIDDEN Year of Reg. 2017  Chassis No. JN1MC2E26Z0008466 Colour SILVER  Odometer 148044 KM Steering IN ORDER  Brakes IN ORDER Modification NIL  General GOOD  Conditions of Tyres			
Engine No. HIDDEN Year of Reg. 2017  Chassis No. JN1MC2E26Z0008466 Colour SILVER  Odometer 148044 KM Steering IN ORDER  Brakes IN ORDER Modification NIL  General GOOD  Conditions of Tyres	2. Vehicle Particulars & Condition		
Chassis No. JN1MC2E26Z0008466 Colour SILVER  Odometer 148044 KM Steering IN ORDER  Brakes IN ORDER Modification NIL  General GOOD  Conditions of Tyres			
Odometer 148044 KM Steering IN ORDER Brakes IN ORDER Modification NIL General GOOD  Conditions of Tyres			
Brakes IN ORDER Modification NIL General GOOD  Conditions of Tyres			
General GOOD  Conditions of Tyres			
3. Conditions of Tyres			
Size Make Balance			
R/H Front Tyre 195 R15C DELIUM 6 mm			
L/H Front Tyre 195 R15C DELIUM 6 mm			
R/H Rear Tyre 195 R15C DELIUM 6 mm			
L/H Rear Tyre 195 R15C DELIUM 6 mm			
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.	4		
DAMAGES SEE DETAILS.			
DAWAGEG GEE DETAILG.	g =		
5. General Information			
Accident Date 27/07/2022 Inspect Date / Time 03/08/2022 ( 09:50 Al	M )		
Survey held at ZOOM AUTOWERKS PTE LTD	,		
130 BEDOK RESERVOIR ROAD, #08-1339,EUNOS SPRING SINGAPORE 470130			
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days			