



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22007370/Rvy3m4	
			Date: 15/09/2022	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SBS 6384D	Veh. Inspected	XE 4281T
	Policy No.	D-19094111MFB	Coverage (\$)	0.00
	Claim No.	D22002355MFBP	Excess (\$)	0.00
	Assign From	CAROLINE CABRERA	Assign Date	02/08/2022
2. Vehicle Particulars & Condition				
	Make & Model	VOLVO FMX370 64R	c.c	10837
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	YV2X922D5JA828207	Colour	RED
	Odometer	362859 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/80 R22.5	TRIANGLE	8 mm
	L/H Front Tyre	235/80 R22.5	TRIANGLE	8 mm
	R/H Rear Tyre	235/80 R22.5 (D/D)	TRIANGLE	8/8 mm
	L/H Rear Tyre	235/80 R22.5 (D/D)	TRIANGLE	8/8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	30/07/2022	Inspection Date	03/08/2022
	Survey held at	SC AUTO INDUSTRIES (S) PTE LTD 51, SENOKO ROAD SINGAPORE 758133		
5a. Remarks				
	A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS. B)DAMAGES CONSISTENT TO ACCIDENT REPORT. C)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. D)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		1 Working Days	