ASS, FEC.BV:	
AS	SIGNMENT
From: Date:	Veh No: 5 4562 CD Yr Regn: 2017 1 Man
Estimaled Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP/WS/TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Toyla Carry. c.c 2494
at Workshop m/s	Colour Wule A/C: Insured / Std / NI / NA
of	Sp.Reading 124378 T/Radio: Insured / Std / NI / NA
nsured	Eng/No:
Policy No.	C/No: MR053AK5004011818
Claims No.	Gen. Cond. Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering:(norder) Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder Jammed / Leaked / Burnt or
Make of Veh:	Modí: Nil /S/Rim STD A/Rim or
	Tyre Size: F: 215/55 RM
(Policy Condition)	R: 215/55RJ,
Remark The veh had commenced its N/S 0/S	BS / DUN / EXNOVA / GY / FS / LIZA MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or
Bal. or Market Value:	Front Rear
DAC Accident Rport: Consistent? : Yes or No	R/Bal. 66 mm R/Bal. 66 mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. Ob mm L/Bal. Ob mm
Est. Repairs:days Res.: Yes or No	D.O.A. D.O.I. 02/08/22
Lum Sum: % 3 Val.: Yes or No	Survey held at HD Pedect.
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / Of Date: Person Contacted:	
Date: Person Contacted:  Date / Time   Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision
TP INC.	•
m∨ :	
PV:	
Nett:	_
·	·
ate/Time, File Pass to?	Davis Of Davis
Preli. Report  : Final Report	Days Of Repair:
Date/Time, File Return to?	Resurvey No. of Trip: Survey Fee:
Add F	Transportation:
7775466 8	
leport Formet:	: Interview (+

SA182281000B / Abwin Service Pte Ltd ENTRY DATE & TIME: 01/08/2022 17:42 (SGT) SUBMITTED BY: Gerine Cheng VERSION: 1 (01/08/2022 17:42 (SGT))



# SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

Please report <u>correctly</u> the details of the accident to speed up the claims process.
 This Form must be <u>completed by the Policyholder and/or the Actual Driver</u>

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## **ACCIDENT STATEMENT**

Date of Submission Reported by Date of Accident **Exact Location of Accident** Additional Location Information Country/State of Loss

01/08/2022 17:42 (SGT) Driver 30/07/2022 14:30 (SGT) Bukit Timah Rd, Singapore BUKIT TIMAH ROAD BEFORE BUKIT TIMAH UNDERPASS Singapore

### **DETAILS OF OWN VEHICLE**

Vehicle Registration Number

S4562CD

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner Company Reg No **Email Address** Mobile Phone No Alternative Phone No.

HIGH COMMISSION DEMOCRATIC SOC REP OF SRI LANKA SXXXXXX045E ADMIN@LANKA.COM.SG (Phone) +65-90619356

VEHICLE PARTICULARS

Manufacturer Model Variant Exact purpose for which vehicle was being used at time of Are you claiming under your own insurance policy for repair to your vehicle? Vehicle Category Transmission CC

Private use

Toyota

Camry

No - Claiming third party Private car Auto 1496

INSURANCE COMPANY

Name of Insurance Company Policy Number / Cover Note Number

NTUC Income Insurance Co-operative Ltd 5109777447-03

DRIVER

Name of Driver Passport No/FIN Date Of Birth Occupation

AJITH WEERASINGHA ARACHCHIGE GXXXX588K 06/11/1975 Outdoor

Date Of Driving Pass 11/05/2021 Driving experience 1 YEAR AND 2 MONTHS Gender Male Mobile Number (Phone) +65-90619356 Alt. Phone Number Email Address ADMIN@LANKA.COM.SG Address 51 GOLDHILL PLAZA Address complement 13-07/12 Postcode 308900 Is the driver the policyholder? No If No, Relationship of the Driver with the Insured Paid Driver Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Chain Collision Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 3 Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) 1 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement DETAILS OF POLICE ACTION Was the accident reported to the police? No

Was the accident reported to the police?

Was notice of intended Prosecution given?

No
If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

### PLEASE REFER TO SKETCH PLAN ATTACHED

ATTACHMENT(S)

Are accident photos available for attachment?

Was there any video captured by Car Camera?

No

#### **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number

Vehicle Manufacturer

Vehicle Model

Vehicle Variant

Vehicle Colour

Vehicle Category

Name of Driver

Contact Number

SMG9815R

Private car

SMG9815R

Private car

Contact Number

Address	_
Address complement	
Postcode	-
Insurance Company Name	
Nature Of Damage	_
Details of property damaged in accident	_
No. Of Passenger (Including Driver)	_

# DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKW1880T
Vehicle Manufacturer	
Vehicle Model	-
Vehicle Variant	_
Vehicle Colour	_
Vehicle Category	Private car
Name of Driver	-
Contact Number	_
Address	-
Address complement	_
Postcode	_
Insurance Company Name	_
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	_

#### SKETCH PLAN

### IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2 This Form must be completed by the Policyholder and/or the Actual Driver
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies
- 5. Any false reporting may be referred to the Traffic Police Department for investigation.
- This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") maylare permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the 'Insurers'), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me,

(iv) administering my claims (including the making of correspondence, statements, invoices, reports or natices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or


(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Porposos; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including the derivers law firms), which may be sited outside of Singapore, for one or more of the above Purposes

SUNDURANCE SOL Sketch Plan









ON THE STATED DATE AND TIME. I, VEHICLE A (S4562CD) WAS TRAVELLING STRAIGHT ON LANE 1 OF BUKIT TIMAH ROAD BEFORE BUKIT TIMAH UNDERPASS. WHEN THE FRONT VEHICLE SLOWED DOWN, I FOLLOWED SUIT WITHOUT HAVING ANY COLLISION WITH THE FRONT VEHICLE. SUDDENLY I FELT A HUGE IMPACT FROM THE REAR PORTION OF MY VEHICLE. AFTER I ALIGHTED I THEN REALISE THAT IS VEHICLE B (SMG9815R) THAT HAD COLLIDED ONTO MY VEHICLE. I WISH TO STATE THAT THIS IS A 3 CARS CHAIN COLLISION.

VEHICLE A: S4562CD

VEHICLE B: SMG9815R

VEHICLE C: SKW1880T





