

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

XE7002M

at Workshop m/s

Moh Lian

of

Insured:

YQ5960K

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$320k.

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

158d

Vehicle: IN / OUT

Date:

Person Contacted:

LTA36645

Veh No:

XE7002M

Yr Regn:

19/01/22

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CM /

Make:

Isuzu CYH52T

c.c

15681

Colour

Green

A/C:

Insured / Std / NI / NA

Sp. Reading

21238

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JALCYH52TM7000117

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

275/70R225B5

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Anate

Front

Rear

R/Bal.

5/5 5/5 mm

R/Bal.

5/5 5/5 mm

L/Bal.

5/5 5/5 mm

L/Bal.

5/5 5/5 mm

D.O.A.

21/06/22

D.O.I.

7/9/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

) S + RS SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	158D
Vehicle Details	
Vehicle No.:	XE7002M
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Sep 2022
Vehicle Make:	ISUZU
Vehicle Model:	CYH52T
Primary Colour:	White
Manufacturing Year:	2021
Engine No.:	6WG1444712
Chassis No.:	JALCYH52TM7000117
Maximum Power Output:	-
Open Market Value:	\$103,209.00
Original Registration Date:	19 Jan 2022
First Registration Date:	19 Jan 2022
Transfer Count:	0
Actual ARF Paid:	\$5,161.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	18 Jan 2032
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$39,139.00
COE Rebate Amount:	\$36,645.00
Total Rebate Amount:	\$36,645.00

The information contained herein is correct as at 07 Sep 2022

OK