

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: FBG 7417A Yr Regn: 10/6/10

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Kawasaki 2G1400C c.c. 1352Colour: Green A/C: Insured / Std / NI / NASp. Reading: 150987 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JKB2GT40CCA 003266Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 170/52R17R: 130/55ZR17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 4 mm R/Bal. 4 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. 28/7/22 D.O.I. 4/8/22Survey held at Role Works

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MR-21K

Date/Time, File Pass to?

☐ : Prell. Report

1) _____

☐ : Final Report

Date/Time, File Return to?

2) _____

Report Formak: _____

Lump Sum / I.B.F. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$ _____

Photos

Others

TOTAL

RACE WERKS PTE LTD

BLK 1008 #01-26 BUKIT MERAH LANE 3 S(159722)

TEL : 6273 2203 FAX : 62730130

REG NO : 201419216K

RE: CLAIM OF ACCIDENT MOTORCYCLE REGN NO: FBG7417A

DATE 02-08-2022

MAKE & MODEL : KAWASAKI GTR1400

ENGINE NO : ZXT40AE061090

CHASSIS NO : JKBZGT40CCA003266

TO CLAIM AGAINST VEHICLE NO: YP872U

(ESTIMATE FOR REPAIR)

1	COWLING, SIDE, LH, C.N.B	✓ CUT	\$ 915.00
1	PAD, CNT COWLING, LH	?	\$ 44.00
1	MIRROR-ASSY, LH, C.N.BL	✓ CUT	\$ 485.00
1	BRACKET, MIRROR	?	\$ 354.00
1	STAY, COWLING, LH	?	\$ 468.00
1	COWLING, LWR, LH, F.S. BLACK	✓ BR	\$ 372.00
1	BRACKET, LWR COWLING, LH	?	\$ 18.00
1	LAMP-TAIL	✓ BR	\$ 318.00
1	COVER, TAIL LAMP, UPP	✓ CUT	\$ 15.00
1	BRACKET (tail lamp)	?	\$ 25.00
1	COVER, TAIL LAMP, LWR	✓ CUT	\$ 21.00
1	FLAP-COMP (Tail tidy)	?	\$ 92.00
1	COVER-TAIL, RR	✓ CRU	\$ 121.00
1	FENDER-FRONT, A.SILVER	✓ BR	\$ 365.00
1	BRACKET-Front FENDER Right	?	\$ 71.00
1	COVER, FRONT FENDER, LH	✓ CUT	\$ 27.00
1	COVER, FRONT FENDER, RH	X	\$ 27.00
1	STEP, FR, RUBBER	X	\$ 105.00
1	STEP, FR, LH	✓ CUT	\$ 55.00
2	SCREW, 5X14	✓ RUC	\$ 48.00
1	BOLT, BANK SENSOR, 6X10	✓ MIS	\$ 12.00
1	SPRING, STEP RETURN	X	\$ 3.00
1	MARK, CNT COWLING, KAWASAKI (LH)	✓ RUC	\$ 197.00
1	STAY, FR, LH, P.SILVER	?	\$ 121.00
1	LAMP-SIGNAL, RR, RH	?	\$ 83.00
1	LAMP-SIGNAL, RR, LH	?	\$ 83.00
2	LEVER-COMP, CHANGE PEDAL	X	\$ 114.00
2	BOLT, 8X41	X	\$ 7.00
1	SPINNER GUIDE	X	\$ 2,450.00
2	WASHER, 12.5X22X1.2	X	\$ 2.00
			\$ 7,018.00

\$ 7,018.00

\$ 6,316.20

SPARE PARTS LESS 10%

RACE WERKS PTE LTD

BLK 1008 #01-26 BUKIT MERAH LANE 3 S(159722)

TEL : 6273 2203 FAX : 62730130

REG NO : 201419216K

SPECIAL-NETT ITEMS (ACCESSORIES)

1	REMUS Street Legal Hexacone Titanium Exhaust With Connection Tube (Kawasaki GTR1400 Concours 07-14) / GR	\$ 1,800.00
1	BAG-ASSY,LH,BODY BLK+ / CM	\$ 1,500.00
1	BAG-ASSY,RH,BODY BLK+ X	\$ 1,500.00
		\$ 4,800.00

SUB TOTAL

COMPUTERIZED FRAME CHECKING

FRAME ALIGNMENT ON BENCH / PROCESS TO FIX BIKE ON BENCH /
PROCESS JIG MEASUREMENT & ALIGNMENT / INSTALL BACK FIXTURE
& RECHECK MEASUREMENT

LOWER CLAIM BALANCING

RENTAL :\$35 PER DAY

Result of Insurance Enquiry - GX1392C

PAINT WORK

LABOUR

TOTAL

\$ 11,116.20	
\$ 350.00	?
\$ 1,250.00	?
\$ 250.00	X
\$ 350.00	X
\$ 7.00	X
\$ 1,200.00	600
\$ 1,200.00	700
\$ 15,723.20	
\$ 1,100.62	7%

ADD GST

7%

GRAND TOTAL

\$ 16,823.82

THIS IS ONLY AN ESTIMATE BASED ON VISUAL INSPECTION.
SHOULD THERE BE MORE DAMAGES FOUND DURING PROCESS, YOU WILL BE
NOTIFIED PRIOR BEFORE WE CARRY OUT FURTHER REPAIR.

Steve (LKK)

4/8/22, 2:00pm

m R

L/S

M A L

S L/S

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SD0A227S0001 / DE XING MOTOR PTE LTD
ENTRY DATE & TIME: 29/07/2022 10:26 (SGT)
SUBMITTED BY: ALUNG WAI WAI
VERSION: 1 (29/07/2022 10:26 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	29/07/2022 10:26 (SGT)
Reported by	Both
Date of Accident	28/07/2022 14:15 (SGT)
Exact Location of Accident	180 Island Club Rd, Singapore 578774
Additional Location Information	NEAR TO SINGAPORE ISLAND COUNTRY CLUB PARKING
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number FBG7417A

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	MOHAMED RIDZUAN BIN MOHAMED BASRI
NRIC No	S7808561D
Email Address	fitness_1978@yahoo.com.sg
Mobile Phone No	(Phone) +65-96688470
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Kawasaki
Model	1400gtr
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Motorcycle
Transmission	Manual
CC	1352

INSURANCE COMPANY

Name of Insurance Company	Direct Asia Insurance (Singapore) Pte Ltd
Policy Number / Cover Note Number	MC/00388027/05

DRIVER

Name of Driver	MOHAMED RIDZUAN BIN MOHAMED BASRI
NRIC No	S7808561D
Date Of Birth	29/03/1978

Date Of Driving Pass
 Driving experience
 Gender
 Mobile Number
 Alt. Phone Number
 Email Address
 Address
 Address complement
 Postcode
 Is the driver the policyholder?
 If No, Relationship of the Driver with the Insured
 Does Driver Own Other Vehicles?
 Vehicle Registration Number of Other Vehicle Owned by Driver
 Insurance Company of Other Vehicle Owned by Driver

25/01/1995
 27 YEARS AND 6 MONTHS
 Male
 (Phone) +65-96688470
 -
 fitness_1978@yahoo.com.sg
 BLK 12C MARSILING LANE
 #12-77
 733012
 Yes
 -
 No
 -
 -

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
 Weather Conditions
 Road Surface

Collided into Parked Vehicle
 AFTER RAIN
 Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?
 Number of vehicles involved in the accident
 Was anybody injured in the Accident?
 Was any injured conveyed to hospital by ambulance?
 Was any other vehicle or property damaged?
 Number of Passengers (Including Driver)
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?
 Translator's name
 Translator's ID
 Translator's phone number
 Translator's email
 Original language used in the statement

No
 2
 No
 -
 Yes
 0
 No
 -
 -
 -
 -
 -

DETAILS OF POLICE ACTION

Was the accident reported to the police?
 Was notice of intended Prosecution given?
 If yes, against whom?

No
 No
 -

CIRCUMSTANCES OF ACCIDENT

AS PER THE SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?
 Was there any video captured by Car Camera?

Yes
 No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number
 Vehicle Manufacturer
 Vehicle Model
 Vehicle Variant
 Vehicle Colour
 Vehicle Category
 Name of Driver
 NRIC No

GX1392C
 -
 -
 -
 -
 Goods vehicle
 MILTON CHUA
 S0079033H

Contact Number	(Phone) +65-96226707
Address	BLK 210 TAMPINES STREET 23
Address complement	#04-97
Postcode	520210
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1

SKETCH PLAN

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies
5. Any false reporting may be referred to the Police for investigation
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.

(ii) investigating the accident and/or my claims

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me,

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages) and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")


(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes


 28/7/2022

Policyholder's Signature / Date & Time
S.S.B

Sketch Plan

 _____
Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel


Joint. FB4 741701
removed.  Plant.
Sketch with cover

Describe Circumstances of the Accident

Motorcycle (FBA 7417N) was parked stationary at the carpark. Lorry (GX 1392C) was reversing and hit motorcycle. Bike drop the side and damaged the thing. Side mirror on the left, crack on taillight and exhaust muffler. The owner (GX 1392C) helps to call the security and placed the bike upright. No injuries but time is wasted. Accident happened at 2.35pm @ 28/7/2023 near to Singapore Island country club parking. Road condition wet after rain.

Declaration

We declare the foregoing particulars are true in every respect.

 28/7/2023
Policyholder's Signature / Date & Time 15:58

Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel