

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





AUTOMOBILE INSPECTION REPORT						
INCOME INSURANCE LTD			Ref:	NS/INC22007441/Gce2		
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	05-10-2022 INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SMS 7971Y	Veh. Ir	nspected	SH 8183K	
	Policy No.		Covera	age (\$)	0.00	
	Claim No.	MT/1182197-002	Exces	s (\$)	0.00	
	Assign From		Assign	n Date	02/08/2022	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA PRIUS	c.c		1798	
	Engine No.	HIDDEN	Year o	f Reg.	2017	
	Chassis No.	JTDKB3FU103565029	Coloui	r	BLUE	
	Odometer	-	Steerii	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	DUNLO		6 mm	
	L/H Front Tyre	195/65 R15	DUNLO		6 mm	
	R/H Rear Tyre	195/65 R15	DUNLO		6 mm	
	L/H Rear Tyre	195/65 R15	DUNLO)P	6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	29/07/2022	Inspec	tion Date	02/08/2022	
	Survey held at	COMFORTDELGRO ENGINEER	FORTDELGRO ENGINEERING PTE LTD			
		59 LOYANG DRIVE SINGAPORE 508969				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days					