




# Service Request Details

Claim

S2M04835

Reference

None 

Loss Date

2 August 2022

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Report Date

3 Aug 2022 11:29:57 AM

Request Date

4 August 2022

Due Date

12 August 2022

Services

Pre-Repair Survey

## Actions

Next Step

Agree to perform service

Accept Work

### Vehicle Information

Incident Vehicle Registration #  
SLW8579G

Make  
TPVD Toyota

Model  
Wish

### Service Address

, , ,

### Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE, 575717, Singapore  
65551188

### Claim Handler

KHOR Saw Theng

sawtheng.khor@axa.com.sg

### Additional Instructions

Messages1

Invoices

History

Documents

Assessment

Metrics

Notes

TYPE

SENT

FROM

SUBJECT

BODY

4/8/22 1:55 PM

LKK AUTO CONSULTANTS PTE LTD (TP)

THANK YOU FOR THE ASSIGNMENT

DEAR KHOR, THANK YOU FOR THE ASSIGNMENT

