

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





| AUTOMOBILE INSPECTION REPORT   |  |  |         |                      |            |  |
|--|--|--|---------|----------------------|------------|--|
| INCOME INSURANCE LTD   |  |  | Ref:    | NS/INC22007446/Gvcm4 |            |  |
| 73 BRAS BASAH ROAD<br>#05-01 NTUC TRADE UNION HOUSESINGAPORE<br>189556 |  |  | Date:   | 22-09-2022<br>INC4   |            |  |
| 1. Policy Particulars :- THIRD PARTY CLAIM                             |  |  |         |                      |            |  |
|  | Insured Veh.   | FBN 3212M  | Veh. Ir | nspected             | SHC 2819G  |  |
|  | Policy No.   |  | Covera  | age (\$)             | 0.00       |  |
|  | Claim No.  | MT/1182841-002                                     | Exces   | s (\$)               | 0.00       |  |
|  | Assign From  |  | Assign  | n Date               | 02/08/2022 |  |
| 2. Vehicle Particulars & Condition                                     |  |  |         |                      |            |  |
|  | Make & Model   | TOYOTA PRIUS                                       | c.c     |                      | 1798       |  |
|  | Engine No.   | HIDDEN   | Year o  | f Reg.               | 2017       |  |
|  | Chassis No.  | JTDKB3FU103569128                                  | Colou   | r                    | BLUE       |  |
|  | Odometer   | -  | Steerin | ng                   | IN ORDER   |  |
|  | Brakes   | IN ORDER   | Modifi  | cation               | NIL        |  |
|  | General  | GOOD   |         |                      |            |  |
| 3. Conditions of Tyres   |  |  |         |                      |            |  |
|  |  | Size   | Make    |                      | Balance    |  |
|  | R/H Front Tyre   | 195/65 R15   | DUNLO   |                      | 6 mm       |  |
|  | L/H Front Tyre   | 195/65 R15   | DUNLO   | P                    | 6 mm       |  |
|  | R/H Rear Tyre  | 195/65 R15   | DUNLO   | P                    | 6 mm       |  |
|  | L/H Rear Tyre  | 195/65 R15   | DUNLO   |                      | 6 mm       |  |
| 4.   | Description of Damages   |  |         |                      |            |  |
|  | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.   |  |         |                      |            |  |
|  | DAMAGES SEE DETAILS.   |  |         |                      |            |  |
| 5. General Information   |  |  |         |                      |            |  |
|  | Accident Date  | 01/08/2022   | Inspec  | tion Date            | 02/08/2022 |  |
|  | Survey held at   | COMFORTDELGRO ENGINEERING PTE LTD                  |         |                      |            |  |
|  |  | 59 LOYANG DRIVE<br>SINGAPORE 508969                |         |                      |            |  |
| 5a.  | Remarks  |  |         |                      |            |  |
|  | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |         |                      |            |  |
| 5b.  | Estimate Days of Repair  |  |         |                      |            |  |
|  | ESTIMATED NOR  | ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days |         |                      |            |  |