

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP ☒ N/S ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV ☐

To Inspect Vehicle No: _____

at Workshop m/s Mr Samonte

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$ _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: BICYCLE - SKZ741C Yr Regn: 2019 /

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or BICYCLE

Make: specialized s-works tarmac c.c. -

Colour: - A/C: Insured / Std / NI / NA

Sp. Reading: - T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair ☒ Poor ☒ BurntSteering: Inorder / ☒ Jammed ☐ Leaked / Burnt orBrake: Inorder / ☒ Jammed ☐ Leaked / Burnt orModi: ☒ Nil ☐ S/Rim / STD A/Rim or

Tyre Size: F: -

R: //

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Roval CL 50

Front

Rear

R/Bal. - mm R/Bal. - mm

L/Bal. - mm L/Bal. - mm

D.O.A. D.O.I. 05-08-2022

Survey held at Savannah CondoPark 4:30PM

Des. of Damages: Frt / ☒ Rea ☐ O/S ☒ N/S ☐ U/C ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Estimate give later

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Insp (\$ _____)☐ : A/Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. SI

Photos

Other:

TOTAL

Report Filed:

Long Cond / MPB: