

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	AXA INSURANCE	PTE LTD		Ref:	CS/ASM22007450/Kcy3m4	
	8 SHENTON WAY SINGAPORE 0688	#24-01 AXA TOWER 11		Date:	08/09/2022	
	ATTN: HO WINNIE			Code:	ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SHB 2991X	Veh. Inspected	d	SKC 323Y	
	Policy No.	VFX/P2419140	Coverage (\$)		0.00	
	Claim No.	S2M04831	Excess (\$)		0.00	
	Assign From	HO WINNIE	Assign Date		04/08/2022	
2.	. Vehicle Particulars & Condition					
	Make & Model	BMW 730LI (A)	c.c		1998	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	WBA7E02040G245272	Colour		METALLIC WHITE	
	Odometer	233609 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	245/50 R18	PIRELLI		6 mm	
	L/H Front Tyre	245/50 R18	PIRELLI		6 mm	
	R/H Rear Tyre	245/50 R18	PIRELLI		6 mm	
	L/H Rear Tyre	245/50 R18	PIRELLI		6 mm	
4.						
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	01/08/2022	Inspection Dat	te	15/08/2022	
	Survey held at	RC AUTO				
		160 SIN MING DRIVE #06-20 SIN MING AUTOCITY SINGAPORE 575722				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days					