

ASS. REC. BY:

REF:

1CS / 22007460/k9

ASS. REI

net.

From:

Estimate

OD

to Ins

Wor

sure

ity

ims

n In

lien

e o'

olic

ark

r

r

r

r

r

r

r

r

r

r

r

r

r

r

r

r

r

r

r

r

r

r

r

r

r

r

r

r

r

r

r

r

r

r

r

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

1. B. / %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBL 517P

Yr Regn:

02 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota

c.c

2982

Colour

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

18927

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTFAT35460K 216278

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: M / S / R / M / STD A / R / M or

Tyre Size:

F:

195R15X8

R:

155R12X8107

SS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

13/7/22

D.O.I.

5/8/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?



: Prell. Report



: Final Report

1)

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

# 来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267  
GST No: M2-0128609-3  
UEN: 199407592C

## ESTIMATE

EST. No ..... EST0029962  
Yong Huat Hardware Pte Ltd

Page ..... 1 of 1  
Your ref. .... TP-SGX 1388R ECICS  
Job No. .... 72910  
Our ref ..... 22.08.04  
Payment .....  
Date ..... 4/8/2022

Attn .....

Vehicle No .... GBL 517P  
Vehicle Model : Toyota Dyna  
Accident on ... 13/7/2022

*Not wither  
Resurvey After Repair  
2 days*

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	DYNA sticker	45.00	25.00	<i>mc</i> 33.75 ✓
Special nett item:					
1.00	Pc	Rear number plate	25.00		<i>mc</i> 25.00 ✓
1.00	Pc	70km/h sticker	10.00		<i>mc</i> 10.00 ✓
Labour & Misc:					
1.00		To replace company logo lettering decal	220.00		<i>mc</i> 220.00 X
1.00		To spray paint on rear tailgate and rear floor end panel	300.00		300.00 <i>260</i>

Sub-Total  
GST 7.00%  
Total

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer 588.75  
Signature: 41.21  
Date: S\$ 629.96

拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。  
还有先进的 SAICO Deluxe 喷漆烘炉。  
services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO oven heater for re-spraying all motor vehicles."



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	14/07/2022 17:52 (SGT)
Reported by	Driver
Date of Accident	13/07/2022 13:14 (SGT)
Exact Location of Accident	Airport Rd, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number GBL517P

#### INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	YONG HUAT HARDWARE PTE LTD
Company Reg No	1XXXXX100W
Email Address	yhhardwarepl@gmail.com
Mobile Phone No	(Phone) +65-62510826
Alternative Phone No	-

#### VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Dyna
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle
Transmission	Manual
CC	2982

#### INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Policy Number / Cover Note Number	DMCVSNW00024742200

#### DRIVER

Name of Driver	Subramanian Brabu
Passport No/FIN	GXXXX165M
Date Of Birth	05/06/1990
Occupation	Outdoor

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
- 6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore (GIA) may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the **Personal Information**) and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the **Insurers**); the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the **Purposes**);
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms) which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature, Date & Time

Driver's Signature (If driver is not the policyholder), Date & Time

Witnessed by Reporting Centre (Personal Name as in NRIC/ID card)

Sketch Plan

