(08/11/13) wef

ASS. REC. BY: Marcus

REF: CC2/MID2200747 8/Up

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLK272G

at Workshop m/s Precise

of

Insured: MID34525

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: $68k.

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

O/S D

Vehicle: IN / OUT

Date: Person Contacted: LTA $36883

Veh No: SLK272G Yr Regn: 05/01/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or CA/

Make: Honda civic c.c 1597

Colour blue A/C: Insured / Std / NI / NA

Sp.Reading 159449 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MRHFC5650GT000749

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ~~Inorder / Jammed / Leaked / Burnt~~ or effected

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/50R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	7 mm	R/Bal.	7 mm
L/Bal.	7 mm	L/Bal.	7 mm
D.O.A.	4/8/22	D.O.I.	5/8/22

Survey held at

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or O/S Frt, O/S Body & Frt.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Dep 13k.
	Nett $31107

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: ($)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Survey Fee:

Transportation: __S + RS, __SI

Photos

Others

TOTAL