

PRS

ASSIGNMENT

From:

Date:

Estimated Cost:

OD ☒ TP ☒ N/S / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s HC AUTO

of

Insured:

Policy No:


Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$38k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: GBD9974K

Yr Regn: 12 Aug/2015

Type: M.Car / M.Cycle / Bus / Van ☒ Lorry ☐ Taxi / Prime Mover /

Truck / Trailer or

Make: MITSUBISHI CANTER c.c. 2998

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 163727 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: FEA01BA10058

Gen. Cond: ☒ Good ☐ Fair / Poor / BurntSteering: ☒ norder ☐ Jammed / Leaked / Burnt orBrake: ☒ norder ☐ Jammed / Leaked / Burnt orModi: ☒ Nil ☐ S/Rim / STD A/Rim or

Tyre Size: F: 195R15

R: //

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FALKEN

Front

Rear

R/Bal. 6 mm R/Bal. 6/6 mm

L/Bal. 6 mm L/Bal. 6/6 mm

D.O.A. D.O.I. 07-07-2022

Survey held at W/S 3:30PM

Des. of Damages: ☒ Frt ☒ Rea ☐ O/S ☐ N/S ☐ U/C ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	\$8000 - \$9000
11/08/2022	Finalise L/S \$6,600.00 ; 8 Days (Red: \$10,120.00 / 61%)
12/09/2022	Submit LS \$6,700.00 ; 8 days (Red: \$10,020.00 ; 60%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Insp (\$☐ : A/Weekend (\$

\$ + RS. SI

Photos

Other:

TOTAL

Report Filed:

Long Cond / MPB: