



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Ref: CS/AGI22007488/Kqy3e2 Date: 29/08/2022	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJS 3822G	Veh. Inspected	SGJ 4895Y
Policy No.		Coverage (\$)	0.00
Claim No.	C10016769/JY	Excess (\$)	0.00
Assign From	MAYBIE CHUA	Assign Date	05/08/2022
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA WISH (A)	c.c	1794
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	ZNE100315874	Colour	METALLIC GREY
Odometer	182968 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	MICHELIN	8 mm
L/H Front Tyre	195/65 R15	MICHELIN	8 mm
R/H Rear Tyre	195/65 R15	MICHELIN	8 mm
L/H Rear Tyre	195/65 R15	MICHELIN	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	04/08/2022	Inspection Date	08/08/2022
Survey held at	POON SIANG SEOW No.160 SIN MING DRIVE #05-13 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	