

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	SOMPO INSURAN	CE SINGAPORE PL	Ref:	CS/SMO22007492/Uqy3q2	
	50 RAFFLES PLAC SINGAPORE LAND	CE #03-03 D TOWERSINGAPORE 048623	Date	: 18/08/2022	
			Code	e: SMO	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJM 2740Y	Veh. Inspected	SJA 7827L	
	Policy No.	D21MTPV01017462	Coverage (\$)	0.00	
	Claim No.	CMTD2202673/MYE	Excess (\$)	0.00	
	Assign From	GRACE TEO	Assign Date	05/08/2022	
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA VANGUARD (A)	c.c	2362	
	Engine No.	HIDDEN	Year of Reg.	2007	
	Chassis No.	ACA335146113	Colour	BLACK	
	Odometer	229568 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	235/65 R17	HABILEAD	6 mm	
	L/H Front Tyre	235/65 R17	HABILEAD	6 mm	
	R/H Rear Tyre	235/65 R17	HABILEAD	6 mm	
	L/H Rear Tyre	235/65 R17	HABILEAD	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	03/08/2022	Inspection Date	05/08/2022	
	Survey held at	FASTECH AUTO PTE LTD			
		1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				