

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

 5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 08/08/2022 17:20 (SGT) Reported by Driver Date of Accident 06/08/2022 14:50 (SGT) Exact Location of Accident Near 15 Tukang Innovation Grove, Singapore 618299 Additional Location Information AT ENTRANCE OF AYE AFTER JALAN AHMAD IBRAHIM Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Hino

4009

Vehicle Registration Number YN7273M

INSURED/POLICYHOLDER

Is company? Yes Name Of Registered Owner MONZONE AIR-CONDITIONING PTE LTD Company Reg No 200102928W Email Address yanyin@monzone-aircon.com Mobile Phone No (Phone) +65-91781315 Alternative Phone No

VEHICLE PARTICULARS

Manufacturer

Model HINO XZU710RIHKFMS3 Exact purpose for which vehicle was being used at time of accident Employment Are you claiming under your own insurance policy for repair to your vehicle? No - Reporting only Vehicle Category Commercial vehicle Transmission Manual

INSURANCE COMPANY

Name of Insurance Company China Taiping Insurance (Singapore) Pte. Ltd. Policy Number / Cover Note Number DMCVSNA00119112101

DRIVER

Name of Driver PIMENTEL MICHAEL GAPOS Passport No/FIN G5016664W Date Of Birth 10/02/1976 Occupation Outdoor

Date Of Driving Pass 29/12/2010 Driving experience 11 YEARS AND 8 MONTHS Gender Mobile Number (Phone) +65-91711436 Alt. Phone Number Email Address monzone@singnet.com.sg Address BLK 221A JURONG EAST ST 21 #08-887 Address complement Postcode 601221 Is the driver the policyholder? Nο If No, Relationship of the Driver with the Insured Hirer Does Driver Own Other Vehicles? Nο Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Head to Rear Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? Nο If yes, against whom? CIRCUMSTANCES OF ACCIDENT ON 06/08/2022 02:50PM, AT ENTRANCE OF AYE AFTER JALAN AHMAD IBRAHIM, I WAS DRIVING AS USUAL SUDDENLY TAXI SHD4248K SUDDEN BRAKE AND I HAVE NO ENOUGH TIME TO BRAKE MY TRUCK, THUS COLLIDE ON THE REAR RIGHT SIDE OF THE VEHICLE. NO INJURY IN THIS CASE. REMARKS: LOCATION NEAR 15 TUKANG INNOVATION GROOVE SINGAPORE 618299 ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes **DETAILS OF OTHER VEHICLE PROPERTY 1** Vehicle Registration Number SHD4248K

Hyundai

Blue

Taxi

Vehicle Model

Vehicle Colour

Vehicle Manufacturer

Vehicle Variant

Vehicle Category

vame of Driver	LAU HUNG SOON
IRIC No	S1588704D
Contact Number	-
Address	-
Address complement	-
Postcode	-
nsurance Company Name	-
lature Of Damage	COLLISION
Details of property damaged in accident	REAR RIGHT DAMAGED
lo. Of Passenger (Including Driver)	1

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 Any false reporting may be referred to the Police for investigation
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association
- of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties,
- 7 By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8 Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that


(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [formi] and any other personal information provided by me or gossessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me:
- (w) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail cackages), and/or
- (7) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my resonal Information for one or more of the above Purposes; and


(c) my Personal information matrican be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including the law yers/law yers), which may be sited outside of Singapore, for one or more of the above Purposes



Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Repurting Centre Personnel





A: SHD YXY8 K

B: YN7273M

On 6/8/2020	r around 2: Sopm, at entrance of AVE after Jalan Ahma
braham, I was ART	ing as usual suddenly tax sto kousk sudden brake and
have no enough to	me to brake my truck, Thus collide on the rear vight sade of
he revode. No my	
Kemenks: Loc	cation near 15 Tukang Innovation Groove Sovyapore 618,799.
NJ	
alation	
declare the foregoing particula	ars are true in every respect.
SAMOTE	NE CO

