



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



AUTOMOBILE INSPECTION REPORT

INCOME INSURANCE LTD

Ref: NS/INC22007562/Tcm4

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE 189556

Date: 07-10-2022

Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SND 3924C	Veh. Inspected	SHD 4324Z
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1184939-003	Excess (\$)	0.00
Assign From		Assign Date	04/08/2022

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI IONIQ	c.c	1580
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	KMHC851CVLU187358	Colour	BLUE
Odometer	366108	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	DURATURN	6 mm
L/H Front Tyre	195/65 R15	DURATURN	6 mm
R/H Rear Tyre	195/65 R15	DURATURN	6 mm
L/H Rear Tyre	195/65 R15	DURATURN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/08/2022	Inspection Date	04/08/2022
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------