

ASS. REC. BY: Tuffin

REF:

INC

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / P / IWS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHD4324Z Yr Regn: 2019/ Oct

Type: M.Car / M.Cycle / Bus / Van / Lorry ⓧ Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Woni c.c. 1580

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 366/08 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KM H1851CVLY 187358

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: W / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Wan + take Duraturn

Front

Rear

R/Bal. 0 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 4/8/22

Survey held at Compt 4 Logis

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Reof top or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Rep. Format: _____

Lump Sum / L.B.L. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. SI _____

Photos _____

Others _____

TOTAL

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHD4324Z
MAKE/REG 25.10.2019

DATE 03.08.2022

CHIANG/NTUC

MODEL : HYUNDAI IONIQ G2

Qty	Parts Description/ Labour	Type	Amount
1	FRONT BUMPER		\$481.10
1	LH SIDE ROCKER GARNISH		\$290.00
1	FRONT DOOR LH		\$1,797.20
1	FRONT DOOR MOULDING LH		\$110.10
1	REAR DOOR LH		\$1,789.90
1	REAR DOOR MOULDING LH		\$125.30
2	WHEEL CAP LH		\$692.80
		\$346.40	
	SUB TOTAL		\$5,286.40
	LESS 20%		\$1,057.28
	DISCOUNTED TOTAL		\$4,229.12
1	REAR DOOR COMFORT APP		\$80.00
1	REAR FENDER ADVERTISEMENT		\$100.00
1	REAR DOOR ADVERTISEMENT		\$100.00
1	FRONT FENDER ADVERTISEMENT		\$100.00
1	FRONT DOOR ADVERTISEMENT		\$100.00
1	FRONT DOOR COMFORT STICKER		\$75.00
	Labour Charge		\$539.50
	Panel Beating		\$1,050.00
	Spray Painting Charge		\$1,300.00
	Remove/Refix rear upholstery		\$90.00
	Remove/refix door parts		\$180.00
	Check Wiring		\$60.00
	TOTAL LABOUR		\$2,680.00
	ESTIMATE TOTAL		\$7,448.62

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s), must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tan JH 97415749

WP 4/8/22 @ 430pm

L/S Kung after repair

Tan JH @ lkkh.com
03 days

Date/Time: 04.08.2022 12:53

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4508008


JC No: 805525495

CUSTOMER R/MS COMFORT TRANSPORTATION PTE LTD CUSTOMER NO. 7010045 ADDRESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 TEL (R) 65508755 (O) (P) SCOUNT CARD NO.	REGN NO. SHD4324Z	MILEAGE
	MAKE HYUNDAI	FUEL E.....1/2.....F
	MODEL IONIQ(G3)	DATE/TIME IN 04.08.2022 08:25
	YR OF MANU. 25.10.2019	TARGET DATE
	CHASSIS CODE KMH851CVLU187358	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 03.08.2022
NATURE: 3P 03.08.2022

/NO	LABOR CODE	DESCRIPTION
-----	------------	-------------



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SHD4324Z
CHIANG

Vehicle No.: SHD4324Z

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard