

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



AUTOMOBILE INSPECTION REPORT						
INCOME INSURANCE LTD			Ref:	NS/INC22007574/Gvcm4		
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	30-09-2022 INC4		
1.		Policy Particulars				
	Insured Veh.	SLT 1849P		nspected	SHA 9598H	
\vdash	Policy No.	- OE1 10401	Covera		0.00	
	Claim No.	MT/1186761-001	Exces	<u> </u>	0.00	
	Assign From		Assign	,	08/08/2022	
2.	Vehicle Particulars & Condition					
	Make & Model	TOYOTA PRIUS	c.c	Condition	1798	
	Engine No.	HIDDEN	Year o	f Rea	2017	
	Chassis No.	JTDKB3FU703557341	Coloui		YELLOW	
	Odometer	702344	Steerin		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make	·	Balance	
	R/H Front Tyre	195/65 R15	DAVAN	ITI	6 mm	
	L/H Front Tyre	195/65 R15	DAVANTI		6 mm	
	R/H Rear Tyre	195/65 R15	DAVANTI		6 mm	
	L/H Rear Tyre	195/65 R15	DAVAN	ΙΤΙ	6 mm	
4.	. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	07/08/2022	Inspec	Inspection Date 08/08/2022		
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD				
		59 LOYANG DRIVE SINGAPORE 508969				
5a. Remarks						
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days					