

ASSIGNMENT

From:

Date:

Estimated Cost:

OD ☒ TP ☒ N/S / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s COMFORTDELGRO

of

Insured: SLT 1849P

Policy No.

Claims No. MT/1186761-001

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SHA9598H

Yr Regn: 31 May/2017

Type: M.Car / M.Cycle / Bus / Van / Lorry ☒ Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA PRIUS c.c 1798

Colour: Yellow A/C: Insured / Std / NI / NA

Sp. Reading: 702344 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTDKB3FU703557341 *

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ norder / Jammed / Leaked / Burnt orBrake: ☒ norder / Jammed / Leaked / Burnt orModi: ☒ Nil / s/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: //

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or DAVANTI

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 7/8/2022 D.O.I. 08-08-2022

Survey held at W/S 12PM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

27/9/22 Guo Qiang informed LS \$850 (Red 1999.45, 70%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 28/9/22-typist

Report Filed: TP

Long Qiang/MPB LS \$850

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Insp (\$)☐ : A/Weekend (\$)

Survey Fee:

Transportation:

S + RS. SI

Photos

Other:

TOTAL