

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/SMR22002579/UC**ASSIGNMENT**

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:


Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:



Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Yr Regn: 24/09/19

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Yr Regn: 24/09/19

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Yr Regn: 24/09/19

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Yr Regn: 24/09/19

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Yr Regn: 24/09/19

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Yr Regn: 24/09/19

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Yr Regn: 24/09/19

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Yr Regn: 24/09/19

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Yr Regn: 24/09/19

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Yr Regn: 24/09/19

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Yr Regn: 24/09/19

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Yr Regn: 24/09/19

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Yr Regn: 24/09/19

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 463R

**Vehicle Details**

Vehicle No.: GBJ8574G

Vehicle to be Exported: No

Intended Deregistration Date: 10 Aug 2022

Vehicle Make: TOYOTA

Vehicle Model: DYNA 150 5MT

Primary Colour: White

Manufacturing Year: 2019

Engine No.: 1KD2860908

Chassis No.: JTFAT35Y50K213808

Maximum Power Output: -

Open Market Value: \$27,082.00

Original Registration Date: 24 Sep 2019

First Registration Date: 24 Sep 2019

Transfer Count: 0

Actual ARF Paid: \$1,355.00

**Intended PARF Rebate Details**

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

**Intended COE Rebate Details**

COE Expiry Date: 23 Sep 2029

COE Category: C - Goods Vehicle &amp; Bus

COE Period(Years): 10

QP Paid: \$25,501.00

COE Rebate Amount: \$18,155.00

**Total Rebate Amount: \$18,155.00**

The information contained herein is correct as at 10 Aug 2022

OK



NEW

ALL CRUNCH, NO GUILT



### Post an Advertisement

Sell it yourself! Advertise it at just  
**\$68 until it's SOLD!**

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Camry 2.0A , 100% Loan by GV CARS FINANCING



Secured Loan by In house  
finance , Warranty packages and  
services available.  
GV Automobile Centre StarAd

AutoInn  
An Inspiration For Car Buyers

click here to view  
our **PRISTINE USED CARS**  
at **GREAT PRICES**

Sort by Date Posted 20 results/page

8 vehicles



Toyota Dyna

Any Category

Advanced Search

Search

Search Selection

Toyota Dyna

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
		Any	Any	2019	Any	Any	Any	Available



#### Toyota Dyna 150 3.0M

\$78,800

\$10,780 /yr

29-Nov-2019

2,982 cc

59,136 km

Truck

Available

Fuel Type: Diesel

1 Owner Unit Only! Low Mileage! Well Maintained By Previous Owner, Purchase With Guaranteed Good Condition. Trade In Welcome, Ba...

Posted: 10-Aug-2022



#### Toyota Dyna 150 3.0M

\$76,800

\$11,420 /yr

30-Apr-2019

2,982 cc

-

Truck

Available

Fuel Type: Diesel

Low mileage 10 feet G plate lorry, come with full canopy and checker plate. New paintwork and loan can be arrange. Call for viewing!

ABWIN (1994) Pte Ltd

Posted: 08-Aug-2022



#### Toyota Dyna 150 3.0M

\$80,800

\$12,370 /yr

19-Feb-2019

2,982 cc

-

Truck

Available

Fuel Type: Diesel

Almost brand new unit! Most Valued 10FT Truck with Thermoking Freezer(-20 Degree) Application Alone (Worth \$25k) Cut down your b...

Car (S) Pte Ltd

Posted: 07-Aug-2022



#### Toyota Dyna 150 3.0M

\$75,800

\$11,760 /yr

18-Jan-2019

2,982 cc

38,530 km

Truck

Available

Fuel Type: Diesel

Tailgate Toyota Dyna with box. Best use for heavy items loading and unloading.Easy to operate by manual or wireless remote control. B...

Posted: 07-Aug-2022



#### Exedy Clutch Kit

Exedy Japan OE Clutch Kit. Available for many car models. Please enquire.

More info about this product



#### Toyota Dyna 150 3.0M

\$78,800

\$11,140 /yr

04-Sep-2019

2,982 cc

47,971 km

Truck

Available

Fuel Type: Diesel

Agent unit! Agent serviced! Cheap and low depreciation! Exclusive engine and gearbox coverage! Fresh paintwork! Original upholstery!...

Car (S) Pte Ltd

Posted: 05-Aug-2022



#### Toyota Dyna 150 3.0M

\$73,888

\$11,300 /yr

22-Feb-2019

2,982 cc

68,960 km

Truck

Available

Fuel Type: Diesel

Well known Toyota Dyna, tip top condition. With checker plate. Please call for more information or WhatsApp for car viewing.

Posted: 30-Jul-2022

Compare



Search Toyota Dyna Price Range Depreciation 2019 Vehicle Type Search Advanced Search

Home » Used Cars » GF Motor Trading Enterprise » Toyota Dyna 150 3.0M

# Toyota Dyna 150 3.0M

Overview Financial Accessories Similar Research Photos Map

Price

\$78,800

Depreciation

\$11,990 /yr  
View models with similar depre

Mileage

N.A.

Road Tax

N.A.

Dereg Value

\$17,330 as of today (change)

COE

\$26,378

Engine Cap

2,982 cc

Curb Weight

1,660 kg

Type of Vehicle

Truck

Reg Date

05-Mar-2019  
(6yrs 6mths 22days COE left)

Manufactured

2019

Transmission

Manual

Fuel Type

Diesel

OMV

\$27,082

ARF

\$1,355

No. of Owners

2

Features

View specs of the Toyota Dyna 150 Diesel (2014)

Description

Fridge just service on early April 2022. Rare 2 side fridge door, please call in advance before viewing. Thanks!

Category

-


Status

Available for sale. Shortlist this car to get alerted whenever the price or availability changes.

Resources

**Vehicle Evaluation**  
Afraid of lemons? Request to have this car evaluated professionally. Find out more

**Car Valuation - Free**  
Find out the market value of your existing car for free. Get started



Price Chart Summary

Click on the point to view the vehicle

Shortlist Compare Report Error More

**Seller Information**  
**GF Motor Trading Enterprise**  
8 vehicles for sale. 9 sold in past 3 mths  
310 Thomson Road  
Eng Aun Mansion  
Tel: 62567600

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	04/08/2022 16:26 (SGT)
Reported by	Driver
Date of Accident	03/08/2022 09:00 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	JALAN ANAK BUKIT FLYOVER TOWARDS DUNEARN ROAD
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number GBJ8574G

#### INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	KAIIOUSEI ENTERPRISE PTE LTD
Company Reg No	200401463R
Email Address	JENNIFERX4325@GMAIL.COM
Mobile Phone No	(Phone) +65-65354566
Alternative Phone No	-

#### VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Dyna
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle
Transmission	Manual
CC	3000

#### INSURANCE COMPANY

Name of Insurance Company	MSIG Insurance (Singapore) Pte. Ltd.
Policy Number / Cover Note Number	B 300354931 MKC

#### DRIVER

Name of Driver	MOHD ALI BIN NOORDIN
NRIC No	S1389543J
Date Of Birth	20/03/1959
Occupation	Outdoor

Date Of Driving Pass	28/09/1991
Driving experience	30 YEARS AND 11 MONTHS
Gender	Male
Mobile Number	(Phone) +65-82625447
Alt. Phone Number	-
Email Address	JENNIFERX4325@GMAIL.COM
Address	BLK 283 YISHUN AVE 6 #10-150 S760283
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	DIZZLING
Road Surface	Wet

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER REPORT ATTACHED

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMB1512T
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-

Address  
Address complement  
Postcode  
Insurance Company Name  
Nature Of Damage  
Details of property damaged in accident  
No. Of Passenger (Including Driver)

-  
-  
-  
-  
-  
-  
-

## DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number YN1396G  
Vehicle Manufacturer -  
Vehicle Model -  
Vehicle Variant -  
Vehicle Colour -  
Vehicle Category Commercial vehicle  
Name of Driver -  
Contact Number -  
Address -  
Address complement -  
Postcode -  
Insurance Company Name -  
Nature Of Damage -  
Details of property damaged in accident -  
No. Of Passenger (Including Driver) -

Describe Circumstances of the Accident


On 08/08/2022 at about 1600hrs, I was travelling along Jalan Anak Bukit Flyover towards Dunearn Road on lane 3. It was drizzling and slow traffic. All vehicles driving slowly in our individual lanes.

Out of a sudden, the vehicle in front of me emergency braked. I stepped on my brake immediately and managed to stop in time.


Unfortunately, Vehicle B braked me from behind. Due to the impact, I inched forward and hit the vehicle in front.

Declaration

I/we declare the foregoing particulars are true in every respect.

 kaiousel enterprise pte ltd  
GST Reg No. 20-0401463-R  
RCB No: 200401463R

Policyholder's Signature / Date & Time

 4/8/22  
3:20pm  
Driver's Signature (if driver is not the policyholder) / Date & Time  
4/8/2022  
1600hrs

  
Witnessed by Reporting Centre Personnel  
4/8/2022  
1600hrs



## SKETCH PLAN

### IMPORTANT NOTICE


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**  
I understand, acknowledge, agree and consent that:
  - (a) My insurer, my workshop and the General Insurance Association of Singapore (GIA) may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
  - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

2  
kaicouei enterprise pte ltd  
GST Reg No. 20-0401463-R  
Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time  
1600/pmr  
4/8/2022

Witnessed by Reporting Centre Personnel  
4/8/2022  
1600

### Sketch Plan



Not Approved  
den  
10/8/22  
4/5 @ 13,000/  
18 days

**FOCUS AUTO PTE LTD**  
1 KAKI BUKIT AVENUE 6 #02-48 / 50  
AUTOBAY @ KAKI BUKIT SINGAPORE 417883  
TEL: 6886 9097 FAX: 6844 4625 Email: claims@focusauto.com.sg

**FIRST CAPITAL INSURANCE LIMITED**

36 Robinson Road  
#16-01  
City House  
Singapore 068877

ATTN : Motor Claim Department  
Your Ref No. : **SMB 1512 T**  
Claim Type : THIRD PARTY  
Accident Date : 03/08/2022

Estimate No : **E22080069**

Date : 10-Aug-22

Veh Reg No : **GBJ 8574 G**

Make / Model : TOYOTA DYNA 150 5MT

Chassis No. : JTFAT35Y50K213808

Engine No. : 1KD2860908

Reg. Date : 24/09/2019

**Estimate Repair Cost for Vehicle No. : GBJ 8574 G**

S/N	Description	Quantity	Unit	Price SS	Amount SS
<b>LIST PRICE</b>					
1	Front Wiper Panel	1	PCS	391.60	783.20
2	Front Corner Panel	2	PCS	339.60	679.20
3	Front Corner Panel Side Bracket - LH	1	PCS	60.20	60.20
4	Front Panel	1	PCS	1196.90	1196.90
5	Front Panel Emblem	1	PCS	70.20	70.20
6	Front Grille	1	PCS	599.60	599.60
7	Front Grille Logo	1	PCS	71.30	71.30
8	Front Grille Clip	1	PCS	12.90	12.90
9	Front Grille Centre Bracket	1	PCS	38.20	38.20
10	Front Cabin Support Bar	1	PCS	786.20	786.20
11	Front Cabin Mounting - LH	1	PCS	489.40	489.40
12	Front Bumper	1	PCS	755.90	755.90
13	Front Bumper Bracket	2	PCS	298.20	596.40
14	Front Bumper Side Cover	2	PCS	102.20	204.40
15	Front Headlamp	2	PCS	1178.70	2357.40
16	Front Side Mirror Bracket	1	PCS	486.20	486.20
17	Front Side Mirror (Big)	1	PCS	326.40	326.40
18	Front Side Mirror (Small)	1	PCS	229.00	229.00
19	Front Side Mirror Bracket Top Garnish	1	PCS	29.20	29.20
20	Front Washer Tank	1	PCS	326.40	326.40
21	Front LH Dash Board Lower Garnish	1	PCS	298.60	298.60
22	Front Dash Board Support Bar	1	PCS	586.20	586.20
23	Front Air Con Blower Cooling Core Assembly	1	PCS	1501.90	1501.90
24	Front Air Con Air Duct Assembly	1	PCS	842.60	842.60
25	Front Door - LH	1	PCS	1712.90	1712.90
26	Front Door Pillar - LH	1	PCS	786.90	786.90
27	Front Door Lock - LH	1	PCS	659.60	659.60
28	Front Door Hinge LH Top	1	PCS	119.60	119.60
29	Front Door Hinge LH Lower	1	PCS	119.60	119.60
30	Front Door Lock Side Panel - LH	1	PCS	682.40	682.40
31	Front Door Rubber - LH	1	PCS	229.60	229.60
32	Front Room Mirror	1	PCS	298.40	298.40
<b>TOTAL A :</b>					<b>18269.10</b>
<b>ADDITIONAL 25% :</b>					<b>4567.28</b>
<b>SUB TOTAL :</b>					<b>13701.83</b>

**SPECIAL NETT**

1	Rear Fridge Door - RH	1	PCS	2000	2000
2	Rear Fridge Door Lock - RH	1	PCS	250	250
3	Rear Fridge Door Hinge - RH	2	PCS	180	360
4	Rear Fridge Door Rubber - RH	1	PCS	180	180

**FOCUS AUTO PTE LTD**

1 KAKI BUKIT AVENUE 6 #02-48 / 50

AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6844 4625 Email: [claims@focusauto.com.sg](mailto:claims@focusauto.com.sg)**FIRST CAPITAL INSURANCE LIMITED**

36 Robinson Road

#16-01

City House

Singapore 068877

ATTN : Motor Claim Department

Your Ref No. : **SMB 1512 T**

Claim Type : THIRD PARTY

Accident Date : 03/08/2022

**Estimate No : E22080069**

Date : 10-Aug-22

Veh Reg No : **GBJ 8574 G**

Make / Model : TOYOTA DYNA 150 5MT

Chassis No. : JTFAT35Y50K213808

Engine No. : 1KD2860908

Reg. Date : 24/09/2019

**Estimate Repair Cost for Vehicle No. : GBJ 8574 G**

S/N	Description	Quantity	Unit	Price	Amount
	<b>SPECIAL NETT</b>			<b>SS</b>	<b>SS</b>
5	Rear Fridge Door Lock - LH <i>11</i>	1	PCS	160	160 X
6	Rear Fridge Door Rubber - LH <i>To 1</i>	1	PCS	180	180 <i>120</i>
7	Rear Fridge Door - LH <i>Che</i>	1	PCS	2000	2000 <i>1400</i>
8	Rear Fridge Door Hinge <i>Scrp</i>	2	PCS	180	180 <i>145</i>
9	Rear Fridge Door Hinge Screw <i>11</i>	16	PCS	20	320 X
10	Rear Fridge Door Screen Frame <i>DD/Scrp</i>	1	PCS	1800	1800 <i>1500</i>
11	Rear Step Bar <i>Scrp</i>	1	PCS	480	480 <i>300</i>
12	Rear Reverse Sensor <i>shorted</i>	1	PCS	300	300 <i>200</i>
13	Rear Fridge Door Sticker 70KM/H <i>del</i>	1	PCS	15	15 <i>10</i>
<b>TOTAL B :</b>					<b>8045.00</b>

**LABOUR CHARGES**

	SS	SS
1 Towing		60.00 <i>50</i>
2 Panel Beating		2000.00 <i>1200</i>
3 To Check Wiring		80.00 <i>30</i>
4 To Remove & Refix Windscreen		140.00 <i>100</i>
5 To Remove & Refix Dash Board		480.00 <i>200</i>
6 To Remove & Refix Air Con Blower Cool Core Assembly, Air Duct and Change Gas		320.00 <i>100</i>
7 To <i>partly &amp; spray painting</i>		1200.00 <i>1180</i>
<b>TOTAL C :</b>		<b>4280.00</b>
<b>A, B &amp; C GRAND TOTAL :</b>		<b>26026.83</b>

**FOR FOCUS AUTO PTE LTD****Jenny Koh****Claims Executive****HP: 8139 9800**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, having resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*P-10751.60*  
*252*  
*8063.70*  
*5340*  
*2860*  
*76263.70*  
*202*  
*13010.86*