



Your Ref: 22.29935

Date: 27th Oct 2022

Our Ref: CS3/ASM21010944/Gqy3e2-1

M/s Axa Insurance Pte Ltd

C/o Seah Ong & Partners LLP

36 Robinson Road #12-03 City House

Singapore 068877

(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: FBS 8346B

INSURED VEHICLE: SHC 8143H

ACCIDENT DATE: 24/10/2021

We thank you for your instruction on 08/08/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of FBS 8346B from M/s C L Appraiser Pte Ltd.
- b) Singapore Accident Statement of Vehicles FBS 8346B and SHC 8143H.
- c) Final Repair Bill of FBS 8346B from M/s HL Cycle PL.
- d) Colour damaged vehicle photographs of FBS 8346B.

Pre-Repair Inspection Date : 26/10/2021 at M/s HL Cycle PL, 1 Kaki Bukit Ave 6 #02-58, Singapore 417883.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: FBS 8346B
Make & Model	: Yamaha XMAX ABS Manual
Year of Registration	: 2021
Chassis Number	: MH3SG3910LK034559
Engine Capacity	: 250 cc

2. We recommend that the repairs of the entire damage require about 3 (Three) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.