

 Service Request Details

Claim	S2M048ML
Reference	CS3/ASM22007646/Sqy3m4 
Loss Date	8 August 2022
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	11 Aug 2022 11:39:53 AM
Request Date	11 August 2022
Due Date	
Services	Pre-Repair Survey

Actions

Next Step

Wait for: Approve invoice

Add Invoice

Vehicle Information

Incident	SMZ3505A
Vehicle	
Registration #	
Make	TPVD - TOYOTA CAMRY
Model	

Service Address

, , ,

Primary Contact/Insured

ENG SOON NG
4 PAVILION GROVE, 658596, Singapore
90301789
MATPOWER@TRANSMAT-TS.COM

Claim Handler

KHOR Saw Theng

sawtheng.khor@axa.com.sg

Additional Instructions

Messages1InvoicesHistoryDocumentsAssessmentMetricsNotes

Document TypeDocument SubType

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice-AC2206817.pdf.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	4 November 2022

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 LKKPreRepairInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	4 November 2022
 LKKPhoto.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	4 November 2022
 AXA Immediate Advice - SMZ3505A (PRS).pdf.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	1 November 2022
 GA607612-Certificate of Insurance.pdf.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of insurance	PODUVAL, Akash	12 August 2022
 GA607612-Policy Schedule.pdf.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of insurance	PODUVAL, Akash	12 August 2022
 TP PRI PDF.pdf.pdf	Letters and Correspondence	Workshop	PODUVAL, Akash	12 August 2022
 TP GIA REPORT.pdf.pdf	Reports & Statement	GIA Report	PODUVAL, Akash	12 August 2022

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 INSD GIA REPORT.pdf.pdf	Reports & Statement	GIA Report	PODUVAL, Akash	12 August 2022
 SS2Z228A0004-SMV5534Z.pdf.pdf	Reports & Statement	Accident statement	STACEY Ng Pei Sze 2	11 August 2022