

Surveyor:

REF: CS1/EQI22007651/Gcy3

Special Instruction:

ASSIGNMENT (Office)

From (Person): JAIME TAY of EQI Date/Time: 11/08/2022

Estimated Cost: Bill to:

\$ 22130.80 / 13 DAYS

Third Parties:

Claimant: IMPACT ANALYSIS

Surveyor: CONSULTANT

Workshop: GARAGE 13 PTE LTD

OD/TP Re-inspection **Evaluation**

To Inspect Vehicle No: SMV 6744C Insured: GBA 5270A

at Workshop m/s GARAGE 13 PTE LTD Tel:

of 8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE.

Policy No: Claim No: DM21HO01520/JT

Sum Insured: Excess:

Make of Veh: D.O.A. 26/09/2021
(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig , days (Red \$ / %; Original 13 days)

Date/Time: Submit Final Fig , days (Red \$ / %; Original days)

Date/Time	Action/Instruction
	SMV 6744C - X
	GBA 5270A - NM/CTI22010360/Sr3 DOA: 15/10/2022
10/11/2022	Submit LS \$7,950.00 ; 7 days (Red. \$14,180.80 ; 64%)

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/
Evaluated by:

Fee Charged:

Basic & Add

Transport

Photos

Others

Total

Date:

1) Date/Time File Pass to

3) Date/Time File Pass to

5) Date/Time File Pass to

2) Date/Time

4) Date/Time

6) Date/Time

File Return to

File Return to

File Return to