

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITA	AL INSURANCE LTD	Ref:	CS/FCI22007654/Rvy3e2
#42-01 HONG LEC	ONG BUILDING	Date:	15/05/2023
		Code:	FCI2
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBE 3906S	Veh. Inspected	GBE 5310Y
Policy No.	D-22099583MFCV/16	Coverage (\$)	0.00
Claim No.	D22002342MFCV	Excess (\$)	0.00
Assign From	JOANNE TAN JO ANN	Assign Date	11/08/2022
2. Vehicle Particulars & Condition			
Make & Model	PEUGEOT PARTNER 1.6 HDI	c.c	1560
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	VF37F9HF8FJ840517	Colour	WHITE
Odometer	146987 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	FIRENZA	6 mm
L/H Front Tyre	195/65 R15	FIRENZA	6 mm
R/H Rear Tyre	195/65 R15	FIRENZA	6 mm
L/H Rear Tyre	195/65 R15	FIRENZA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	28/07/2022	Inspection Date	12/08/2022
Survey held at	AUTO INSURE PTE LTD		
	6 MARSILING LANE S739145		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days			
	Insured Veh. Policy No. Claim No. Assign From Make & Model Engine No. Chassis No. Odometer Brakes General R/H Front Tyre L/H Front Tyre L/H Rear Tyre L/H Rear Tyre THE VEHICLE SUIDAMAGES SEE D Accident Date Survey held at A)DAMAGES CON B)THE INSPECTION C)IN ACCORDANG	MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581 Policy Particulars Insured Veh. GBE 3906S Policy No. D-22099583MFCV/16 Claim No. D22002342MFCV Assign From JOANNE TAN JO ANN Vehicle Partic Make & Model PEUGEOT PARTNER 1.6 HDI Engine No. HIDDEN Chassis No. VF37F9HF8FJ840517 Odometer 146987 KM Brakes IN ORDER General FAIR Conditi Size R/H Front Tyre 195/65 R15 L/H Rear Tyre 195/65 R15 L/H Rear Tyre 195/65 R15 L/H Rear Tyre 195/65 R15 CHROMAGES SEE DETAILS. General Accident Date 28/07/2022 Survey held at AUTO INSURE PTE LTD 6 MARSILING LANE 8739145 Re A)DAMAGES CONSISTENT TO ACCIDENT REPOR B)THE INSPECTION WAS CONDUCTED ON A"WIT C)IN ACCORDANCE TO YOUR INSTRUCTIONS, W Estimate	MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581 Code: Policy Particulars: - THIRD PARTY CLAIN Insured Veh. GBE 3906S Veh. Inspected Policy No. D-22099583MFCV/16 Coverage (\$) Claim No. D22002342MFCV Excess (\$) Assign From JOANNE TAN JOANN Assign Date Vehicle Particulars & Condition Make & Model PEUGEOT PARTNER 1.6 HDI c.c Engine No. HIDDEN Year of Reg. Chassis No. VF37F9HF8FJ840517 Colour Odometer 146987 KM Steering Brakes IN ORDER Modification General FAIR Conditions of Tyres Size Make R/H Front Tyre 195/65 R15 FIRENZA L/H Front Tyre 195/65 R15 FIRENZA L/H Rear Tyre 195/65 R15 FIRENZA L/H Rear Tyre 195/65 R15 FIRENZA L/H Rear Tyre 195/65 R15 FIRENZA THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. General Information Accident Date 28/07/2022 Inspection Date Survey held at AUTO INSURE PTE LTD 6 MARSILING LANE 8739145 Remarks A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASICINA ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISI