(08/11/13) wbf

ASS. REC. BY: Jane

REF: CS/EQI22007667/Rny3

S 074C

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMT 7221Z

at Workshop m/s VOLKSWAGEN

of 247, ALEXANDRA RD

Insured: EQI

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 124K

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 1 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SMT 7221Z Yr Regn: 2010, July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: VOLKSWAGEN PASSAT 1.8TFSI c.c 1798

Colour BLACK A/C: Insured / Std / NI / NA

Sp.Reading 44347 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WVWZZZ3C2KE130542

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55R17

R: ~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	05/08/22	D.O.I.	19/08/22

Survey held at VOLKSWAGEN

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or o/s front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 7.1K

22/09/22 Rasul confirmed final fig $2227.25 and 1 days (red, 1190.10, 35%)

Date/Time, File Pass to? ☐ : Preli. Report

1) 22/09/22 ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 1

Resurvey No. of Trip: 1

Survey Fee:

Transportation: S + RS: SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Report Format :

Lump Sum / I.B.I: ($ 2227.25)