



Service Request Details

Claim

S2M0489D

Reference

None 

Loss Date

4 August 2022

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Report Date

5 Aug 2022 10:51:24 AM

Request Date

12 August 2022

Due Date

19 August 2022

Services

Pre-Repair Survey

Actions

Next Step

Agree to perform service

Accept Work

Vehicle Information

Incident Vehicle Registration #

FBQ9256G

Make

TPVD Honda

Model

CB190SS

Service Address

'''

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

OH Vale

vale.oh@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

 Document SubType

 Upload Documents

Already Attached

NAME	 FBQ9256G TP GIA.pdf.pdf
TYPE	Reports & Statement
SUBTYPE	GIA Report
AUTHOR	NIKAM Santosh Pandurang
DATE UPLOADED	12 August 2022

NAME	 EMAIL FORM SOLICITOR FOR TP REG.msg.msg
TYPE	Letters and Correspondence
SUBTYPE	Others
AUTHOR	NIKAM Santosh Pandurang
DATE UPLOADED	12 August 2022

NAME	 SJ0G2284000J-SHA7019B.pdf.pdf
TYPE	Reports & Statement
SUBTYPE	Accident statement
AUTHOR	STACEY Ng Pei Sze 2
DATE UPLOADED	5 August 2022
