

(08/11/13) wef

ASS. REC. BY: PKM

REF: CS3/CTI 22007697/R93

9352

CSX1124:2029/09

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: YN686B

at Workshop m/s RIGHT CLICK AUTOWORKS

of 7,800N LEE ST #01-27 @ 1SPACE

Insured: CTI

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: 53K

IDAC Accident Rport: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: YN686B Yr Regn: 2009 10C1

Type: M.Car / M.Cycle / Bus / Van / (Lorry) / Taxi / Prime Mover /

Truck / Trailer or

Make: ISUZU NPR85UHSA c.c 2999

Colour WHITE A/C: Insured / Std / NI / NA

Sp.Reading 575905 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JAA NPR85H97100325

Gen. Cond: Good / (Fair) / Poor / Burnt

Steering: (In order) / Jammed / Leaked / Burnt or

Brake: (In order) / Jammed / Leaked / Burnt or

Modi: (Nil) / S/Rim / STD A/Rim or

Tyre Size: F: 7.00R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / (SUMI)

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7/7 mm

L/Bal. 7 mm L/Bal. 7/7 mm

D.O.A. 02/08/22 D.O.I. 24/08/22

Survey held at RIGHT CLICK AUTO

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S FR

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 34K

ESTIMATE RANGE OF REPAIR / NO. OF DAYS - (4K-5K) / 4 days

Date/Time, File Pass to?

: Prell. Report

1)

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: : Site Insp (\$

: Interview (\$

: Tech. Invs (\$

) S + RS, SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I: (\$ _____)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 935C

Vehicle Details

Vehicle No.: YN686B

Vehicle to be Exported: No

Intended Deregistration Date: 28 Aug 2022

Vehicle Make: ISUZU

Vehicle Model: NPR85UH5A

Primary Colour: White

Manufacturing Year: 2009

Engine No.: 4JJ1821003

Chassis No.: JAANPR85H97100325

Maximum Power Output: -

Open Market Value: \$36,156.00

Original Registration Date: 26 Oct 2009

First Registration Date: 26 Oct 2009

Transfer Count: 0

Actual ARF Paid: \$1,808.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 30 Sep 2029

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

PQP Paid: \$25,832.00

COE Rebate Amount: \$18,312.00

Total Rebate Amount: \$18,312.00

The information contained herein is correct as at 28 Aug 2022

OK