

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

8 SHENTON WAY #24-01 D AXA TOWERSINGAPORE 068811	ate: ode: :LAIM	
AXA TOWERSINGAPORE 068811 ATTN:CYNTHIA C 1. Policy Particulars :- THIRD PARTY C Insured Veh. SHB 2139R Veh. Inspected	ode:	ASM SLK 4528T 0.00
1. Policy Particulars :- THIRD PARTY Consumer Veh. SHB 2139R Veh. Inspected	LAIM	SLK 4528T 0.00
Insured Veh. SHB 2139R Veh. Inspected		SLK 4528T 0.00
mount of the second		0.00
Policy No. P2465703 Coverage (\$)		
		0.00
Claim No. S2M048R9 Excess (\$)		
Assign From Assign Date		12/08/2022
2. Vehicle Particulars & Condition		
Make & Model HONDA VEZEL HYBRID c.c		1496
Engine No. HIDDEN Year of Reg.		2017
Chassis No. RU31216032 Colour		BRONZE
Odometer 195807 KM Steering		IN ORDER
Brakes IN ORDER Modification		SPORTS RIM
General GOOD		
3. Conditions of Tyres		
Size Make		Balance
R/H Front Tyre 215/60 R16 CRUCERO		6 mm
L/H Front Tyre 215/60 R16 CRUCERO		6 mm
R/H Rear Tyre 215/60 R16 CRUCERO		6 mm
L/H Rear Tyre 215/60 R16 CRUCERO		6 mm
4. Description of Damages		
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.		
DAMAGES SEE DETAILS.		
5. General Information		
Accident Date 11/08/2022 Inspection Date		12/08/2022
Survey held at JL PERFECT AUTOWORK PTE LTD		
8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		
5a. Remarks		
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		
5b. Estimate Days of Repair		
ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days		