

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Make & ModelNISSAN NV200 (M)c.c1461Engine No.HIDDENYear of Reg.2018Chassis No.VSKYBAM20Z0173217ColourWHITE / ORANGEOdometer106494 KMSteeringIN ORDERBrakesIN ORDERModificationNILGeneralGOOD	DAMAGE ASSESSMENT REPORT						
#05-01 NTUC TRADE UNION HOUSESINGAPORE 189556 ATTN: CHESTER CHONG Code: INC No.		NTUC INCOME INSURANCE CO-OPERATIVE LTD			CS/INC22007741/Uqy3e2		
Insured Veh. SKD 3995H Veh. Inspected GBH 8497G		#05-01 NTUC TRA		Date:	26/08/2022		
Insured Veh. SKD 3995H		ATTN: CHESTER (CHONG	Code	INC		
Policy No. Coverage (\$) 0.00	1.		Policy Particulars	- THIRD PARTY CLAI	M		
Claim No. MT/1180957-002 Excess (\$) 0.00 Assign From DIANA TAY Assign Date 15/08/2022		Insured Veh.	SKD 3995H	Veh. Inspected	GBH 8497G		
Assign From		Policy No.		Coverage (\$)	0.00		
Name		Claim No.	MT/1180957-002	Excess (\$)	0.00		
Make & Model NISSAN NV200 (M) C.C 1461		Assign From	DIANA TAY	Assign Date	15/08/2022		
Engine No. HIDDEN Year of Reg. 2018	2. Vehicle Particulars & Condition						
Chassis No. VSKYBAM20Z0173217 Colour WHITE / ORANGE Odometer 106494 KM Steering IN ORDER Brakes IN ORDER Modification NIL General GOOD		Make & Model	NISSAN NV200 (M)	c.c	1461		
Odometer 106494 KM Steering IN ORDER		Engine No.	HIDDEN	Year of Reg.	2018		
Brakes IN ORDER Modification NIL General GOOD 3. Conditions of Tyres Size Make Balance R/H Front Tyre 175/70 R14 COMFOREST 6 mm L/H Front Tyre 175/70 R14 COMFOREST 6 mm R/H Rear Tyre 175/70 R14 COMFOREST 6 mm L/H Rear Tyre 175/70 R14 COMFOREST 6 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS. 5. General Information Accident Date 19/07/2022 Inspect Date / Time 15/08/2022 (01:23 PM) Survey held at ETHOZ GROUP LTD 22 TAMPINES STREET 92 SINGAPORE 528876 5a. Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. 5b. Estimate Days of Repair		Chassis No.	VSKYBAM20Z0173217	Colour	WHITE / ORANGE		
General GOOD 3. Conditions of Tyres Size Make Balance		Odometer	106494 KM	Steering	IN ORDER		
3. Conditions of Tyres R/H Front Tyre		Brakes	IN ORDER	Modification	NIL		
R/H Front Tyre 175/70 R14 COMFOREST 6 mm L/H Front Tyre 175/70 R14 COMFOREST 6 mm R/H Rear Tyre 175/70 R14 COMFOREST 6 mm L/H Rear Tyre 175/70 R14 COMFOREST 6 mm L/H Rear Tyre 175/70 R14 COMFOREST 6 mm L/H Rear Tyre 175/70 R14 COMFOREST 6 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS. 5. General Information Accident Date 19/07/2022 Inspect Date / Time 15/08/2022 (01:23 PM) Survey held at ETHOZ GROUP LTD 22 TAMPINES STREET 92 SINGAPORE 528876 5a. Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. 5b. Estimate Days of Repair		General	GOOD				
R/H Front Tyre 175/70 R14 COMFOREST 6 mm L/H Front Tyre 175/70 R14 COMFOREST 6 mm R/H Rear Tyre 175/70 R14 COMFOREST 6 mm L/H Rear Tyre 175/70 R14 COMFOREST 6 mm L/H Rear Tyre 175/70 R14 COMFOREST 6 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS. 5. General Information Accident Date 19/07/2022 Inspect Date / Time 15/08/2022 (01:23 PM) Survey held at ETHOZ GROUP LTD 22 TAMPINES STREET 92 SINGAPORE 528876 5a. Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. 5b. Estimate Days of Repair	3.		Condition	ons of Tyres			
L/H Front Tyre 175/70 R14 COMFOREST 6 mm R/H Rear Tyre 175/70 R14 COMFOREST 6 mm L/H Rear Tyre 175/70 R14 COMFOREST 6 mm L/H Rear Tyre 175/70 R14 COMFOREST 6 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS. 5. General Information Accident Date 19/07/2022 Inspect Date / Time 15/08/2022 (01:23 PM) Survey held at ETHOZ GROUP LTD 22 TAMPINES STREET 92 SINGAPORE 528876 5a. Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. 5b. Estimate Days of Repair			Size	Make	Balance		
R/H Rear Tyre 175/70 R14 COMFOREST 6 mm L/H Rear Tyre 175/70 R14 COMFOREST 6 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS. 5. General Information Accident Date 19/07/2022 Inspect Date / Time 15/08/2022 (01:23 PM) Survey held at ETHOZ GROUP LTD 22 TAMPINES STREET 92 SINGAPORE 528876 5a. Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. 5b. Estimate Days of Repair		R/H Front Tyre	175/70 R14	COMFOREST	6 mm		
L/H Rear Tyre 175/70 R14 COMFOREST 6 mm 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS. 5. General Information Accident Date 19/07/2022 Inspect Date / Time 15/08/2022 (01:23 PM) Survey held at ETHOZ GROUP LTD 22 TAMPINES STREET 92 SINGAPORE 528876 5a. Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. 5b. Estimate Days of Repair		L/H Front Tyre	175/70 R14	COMFOREST	6 mm		
4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS. 5. General Information Accident Date 19/07/2022 Inspect Date / Time 15/08/2022 (01:23 PM) Survey held at ETHOZ GROUP LTD 22 TAMPINES STREET 92 SINGAPORE 528876 5a. Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. 5b. Estimate Days of Repair		R/H Rear Tyre	175/70 R14	COMFOREST	6 mm		
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS. 5. General Information Accident Date 19/07/2022 Inspect Date / Time 15/08/2022 (01:23 PM) Survey held at ETHOZ GROUP LTD 22 TAMPINES STREET 92 SINGAPORE 528876 5a. Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. 5b. Estimate Days of Repair		L/H Rear Tyre	175/70 R14	COMFOREST	6 mm		
5. General Information Accident Date 19/07/2022 Inspect Date / Time 15/08/2022 (01:23 PM) Survey held at ETHOZ GROUP LTD 22 TAMPINES STREET 92 SINGAPORE 528876 5a. Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. 5b. Estimate Days of Repair	4.	4. Description of Damages					
5. General Information Accident Date 19/07/2022 Inspect Date / Time 15/08/2022 (01:23 PM) Survey held at ETHOZ GROUP LTD 22 TAMPINES STREET 92 SINGAPORE 528876 5a. Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. 5b. Estimate Days of Repair		THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION					
5. General Information Accident Date 19/07/2022 Inspect Date / Time 15/08/2022 (01:23 PM) Survey held at ETHOZ GROUP LTD 22 TAMPINES STREET 92 SINGAPORE 528876 5a. Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. 5b. Estimate Days of Repair							
Accident Date 19/07/2022 Inspect Date / Time 15/08/2022 (01:23 PM) Survey held at ETHOZ GROUP LTD 22 TAMPINES STREET 92 SINGAPORE 528876 5a. Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. 5b. Estimate Days of Repair		DAMAGES SEE DETAILS.					
Accident Date 19/07/2022 Inspect Date / Time 15/08/2022 (01:23 PM) Survey held at ETHOZ GROUP LTD 22 TAMPINES STREET 92 SINGAPORE 528876 5a. Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. 5b. Estimate Days of Repair	_						
Survey held at ETHOZ GROUP LTD 22 TAMPINES STREET 92 SINGAPORE 528876 5a. Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. 5b. Estimate Days of Repair	5.				45 (00 (0000 / 04 00 DNA)		
22 TAMPINES STREET 92 SINGAPORE 528876 5a. Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. 5b. Estimate Days of Repair				Inspect Date / Time	15/08/2022 (U1:23 PM)		
5a. Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. 5b. Estimate Days of Repair		- u. v y. v u. u. v					
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. 5b. Estimate Days of Repair	Eo						
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. 5b. Estimate Days of Repair	oa.	A)THE INSPECTIO			19		
,							
ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days	5b.		Estimate l	Days of Repair			
		ESTIMATED NORI	MAL PERIOD FOR REPAIR:	3 Wor	king Days		