

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	INCOME INSURAN	ICE LTD		Ref:	CS/INC22007750/Acy3e2	
	73 BRAS BASAH F #05-01 NTUC TRA 189556	ROAD DE UNION HOUSESINGAPORE		Date:	06/10/2022	
	ATTN: CHARLOTT	E CHEW		Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMF 8724G	Veh. Inspected	l	SLB 9192S	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1183830-002	Excess (\$)		0.00	
	Assign From	DIANA TAY	Assign Date		15/08/2022	
2. Vehicle Particulars & Condition						
	Make & Model	KIA FORTE K3	c.c		1591	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	KNAFZ411MG5601047	Colour		WHITE	
	Odometer	71364 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	215/45 R17	ROADSTONE		6 mm	
	L/H Front Tyre	215/45 R17	ROADSTONE		6 mm	
	R/H Rear Tyre	215/45 R17	ROADSTONE		6 mm	
	L/H Rear Tyre	215/45 R17	ROADSTONE		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	11/08/2022	Inspect Date /	Time	15/08/2022 (11:19 AM)	
	Survey held at	SM AUTOMOTIVE				
	BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883					
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.		Estimate Days of Repair				
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:		9 Worki	ing Days	