

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

GREAT AMERICAN INSURANCE COMPANY   Ref: CS/GAI22007753/Rcy3e2   3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190   Code: GAI	Affiliated to Federation Internationale Des Experts En Automobile						
#16-01 CENTENNIAL TOWER SINGAPORE 039190  Code: GAI  Policy Particulars: - THIRD PARTY CLAIM  Insured Veh. GBB 7597P		GREAT AMERICA	N INSURANCE COMPANY	Ref:	CS/GAI22007753/Rcy3e2		
Insured Veh.   GBB 7597P   Veh. Inspected   SNC 8972K		#16-01 CENTENN	IAL TOWER	Date	e: 29/12/2022		
Insured Veh.   GBB 7597P				Cod	e: GAI		
Policy No.   Coverage (\$)   0.00	1.	. Policy Particulars :- THIRD PARTY CLAIM					
Claim No.   CLMOMVC000004209   Excess (\$)   0.00     Assign From   SHERY WONG   Assign Date   15/08/2022     2.   Vehicle Particulars & Condition     Make & Model   KIA NIRO HYBRID 1.6 DCT   C.C   1580     SUNROOF   Clour   BLACK     Chassis No.   KNACC81CVN5511969   Colour   BLACK     Odometer   28675 KM   Steering   IN ORDER     Brakes   IN ORDER   Modification   SPORTS RIM     General   FAIR     3.   Conditions of Tyres		Insured Veh.	GBB 7597P	Veh. Inspected	SNC 8972K		
Assign From   SHERY WONG   Assign Date   15/08/2022		Policy No.		Coverage (\$)	0.00		
Make & Model         KIA NIRO HYBRID 1.6 DCT SUNROOF         c.c         1580           Engine No.         HIDDEN         Year of Reg.         2021           Chassis No.         KNACC81CVN5511969         Colour         BLACK           Odometer         28675 KM         Steering         IN ORDER           Brakes         IN ORDER         Modification         SPORTS RIM           General         FAIR         FAIR           3.         Conditions of Tyres           R/H Front Tyre         205/60 R16         MICHELIN         6 mm           L/H Front Tyre         205/60 R16         MICHELIN         6 mm           R/H Rear Tyre         205/60 R16         MICHELIN         6 mm           L/H Rear Tyre         205/60 R16         MICHELIN         6 mm           4.         Description of Damages           THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.         DAMAGES SEE DETAILS.           5.         General Information           Accident Date         25/07/2022         Inspection Date         24/08/2022		Claim No.	CLMOMVC000004209	Excess (\$)	0.00		
Make & Model         KIA NIRO HYBRID 1.6 DCT SUNROOF         c.c         1580           Engine No.         HIDDEN         Year of Reg.         2021           Chassis No.         KNACC81CVN5511969         Colour         BLACK           Odometer         28675 KM         Steering         IN ORDER           Brakes         IN ORDER         Modification         SPORTS RIM           General         FAIR         FAIR           3.         Conditions of Tyres           Size         Make         Balance           R/H Front Tyre         205/60 R16         MICHELIN         6 mm           L/H Front Tyre         205/60 R16         MICHELIN         6 mm           R/H Rear Tyre         205/60 R16         MICHELIN         6 mm           L/H Rear Tyre         205/60 R16         MICHELIN         6 mm           4.         Description of Damages           THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.         DAMAGES SEE DETAILS.           5.         General Information           Accident Date         25/07/2022         Inspection Date         24/08/2022		Assign From	SHERY WONG	Assign Date	15/08/2022		
SUNROOF	2. Vehicle Particulars & Condition						
Chassis No.   KNACC81CVN5511969   Colour   BLACK		Make & Model		c.c	1580		
Odometer		Engine No.	HIDDEN	Year of Reg.	2021		
Brakes   IN ORDER   Modification   SPORTS RIM		Chassis No.	KNACC81CVN5511969	Colour	BLACK		
General   FAIR		Odometer	28675 KM	Steering	IN ORDER		
3. Conditions of Tyres    Size   Make   Balance		Brakes	IN ORDER	Modification	SPORTS RIM		
Size   Make   Balance		General	FAIR				
R/H Front Tyre 205/60 R16 MICHELIN 6 mm  L/H Front Tyre 205/60 R16 MICHELIN 6 mm  R/H Rear Tyre 205/60 R16 MICHELIN 6 mm  L/H Rear Tyre 205/60 R16 MICHELIN 6 mm  L/H Rear Tyre 205/60 R16 MICHELIN 6 mm  4. Description of Damages  THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.  DAMAGES SEE DETAILS.  5. General Information  Accident Date 25/07/2022 Inspection Date 24/08/2022	3.	3. Conditions of Tyres					
L/H Front Tyre   205/60 R16   MICHELIN   6 mm   R/H Rear Tyre   205/60 R16   MICHELIN   6 mm   L/H Rear Tyre   205/60 R16   MICHELIN   6 mm   4.			Size	Make	Balance		
R/H Rear Tyre 205/60 R16 MICHELIN 6 mm  L/H Rear Tyre 205/60 R16 MICHELIN 6 mm  4. Description of Damages  THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.  DAMAGES SEE DETAILS.  5. General Information  Accident Date 25/07/2022 Inspection Date 24/08/2022		R/H Front Tyre	205/60 R16	MICHELIN	6 mm		
L/H Rear Tyre 205/60 R16 MICHELIN 6 mm  4. Description of Damages  THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.  DAMAGES SEE DETAILS.  5. General Information  Accident Date 25/07/2022 Inspection Date 24/08/2022		L/H Front Tyre	205/60 R16	MICHELIN	6 mm		
4. Description of Damages  THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.  DAMAGES SEE DETAILS.  5. General Information  Accident Date 25/07/2022 Inspection Date 24/08/2022		R/H Rear Tyre	205/60 R16	MICHELIN	6 mm		
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.  DAMAGES SEE DETAILS.  5. General Information  Accident Date 25/07/2022 Inspection Date 24/08/2022		L/H Rear Tyre	205/60 R16	MICHELIN	6 mm		
DAMAGES SEE DETAILS.  5. General Information  Accident Date 25/07/2022 Inspection Date 24/08/2022	4.						
5. General Information Accident Date 25/07/2022 Inspection Date 24/08/2022		THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.					
Accident Date 25/07/2022 Inspection Date 24/08/2022		DAMAGES SEE D	ETAILS.				
1 '	5.		General	Information			
Survey held at CYCLE & CARRIAGE AUTOMOTIVE PTE LTD		Accident Date	25/07/2022	Inspection Date	24/08/2022		
		Survey held at	CYCLE & CARRIAGE AUTOMO				
209 PANDAN GARDENS SINGAPORE 609339							
5a. Remarks	5a.						
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.							
5b. Estimate Days of Repair	5b.						
ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days							