

ASS. REC BY: stere

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bel. or Market Value: _____
IDAC Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SK 6313IT Yr Regn: 21/6/14
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: BMW 4781 cc 1997
Colour: Black A/C: Insured / Std / NI / NA
Sp. Reading: 77534 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: WBA3V320805993445
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modl: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 225/45R18
R: 11
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Cinturato
Front
R/Bal. 4 mm R/Bal. 4 mm
L/Bal. 4 mm L/Bal. 4 mm
D.O.A. 14/8/22 D.O.I. 17/8/22
Survey held at Goldbell
Des. of Damages: (Frt) Rear / O/S / N/S / U/C / Rooftop or
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>MTV-89K</u>

Date/Time, File Pass to? ☐ : Prel. Report
Date/Time, File Return to? ☐ : Final Report

2) _____
Report Format: _____
Lump Sum / L.B.F. (\$) _____

Days Of Repair: _____
Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:
Transportation: _____
\$ + RS. \$
Photos _____
Others _____
TOTAL _____



GOLDBELL ENGINEERING

Industrial Vehicles. Financial Services.
41,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD
Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3676
Finance: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500
Website: www.goldbell.com.sg
Co Reg No: 198003963G

Page 1 / 2

ESTIMATE

Date : 16/08/2022
To : INDIA INTERNATIONAL INSURANCE
PTE LTD
Attn. :
Office / Mobile :
Email Address :
From : GOLDBELL ENGINEERING PTE LTD
Attn. : CATHERINECHONGKL
Office / Mobile :
Email / Fax No. : CatherineChongKL@goldbell.com.sg

Reg No : SKG3131T
Model : B.M.W. / 428I CONVERTIBLE
AT D/AB HID NAV HUD
Chassis No : WBA3V32080J993445
Engine No : A7850806N20B20A
Quotation No. : 162296
Ref. No. : GBE/SVC/SALES-HQ/218-1408
D.O.A. : 14/08/2022
Policy No. : DMPCSNW00236892100
Claim Type : TP CLAIM - INDIA
INTERNATIONAL INSURANCE
Workshop : 8 TUAS AVE 18

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
1		FRONT BUMPER / CRU	1	1,340.47	-5	1,273.45	1,273.45
2		FRONT BUMPER LOWER CENTRE COVER ?	1	74.75	-5	71.01	71.01
3		FRONT BUMPER PARKING SENSOR HOLDER SET / MC	1	107.20	-5	101.84	101.84
4		FRONT BUMPER SENSOR ?	4	254.35	-5	241.63	966.53
5		FRONT RADIATOR GRILLE - BR	2	165.15	-5	156.89	156.89
6		FRONT LOWER GRILLE - BR	1	183.75	-5	174.56	174.56
7		BMW BADGE - MC	1	90.50	-5	85.98	85.98
8		FOG LAMP LH ?	1	306.95	-5	291.60	291.60
9		FOG LAMP RH ?	1	306.95	-5	291.60	291.60
10		FOG LAMP TRIM LH - BR	1	145.80	-5	138.51	138.51
11		FOG LAMP TRIM RH - BR	1	145.80	-5	138.51	138.51
12		FOG LAMP COVER LH - MIS	1	112.30	-5	106.69	106.69
13		FOG LAMP COVER RH - MIS	1	112.30	-5	106.69	106.69
14		HEADLAMP LH - CUT	1	2,162.30	-5	2,054.19	2,054.19
15		HEADLAMP RH - CUT	1	2,162.30	-5	2,054.19	2,054.19
16		HEADLAMP WASHER COVER LH X	1	107.20	-5	101.84	101.84
17		HEADLAMP WASHER COVER RH X	1	107.20	-5	101.84	101.84
18		FOG LAMP INNER BRACKET LH X	1	63.45	-5	60.28	60.28
19		FOG LAMP INNER BRACKET RH X	1	63.45	-5	60.28	60.28
20		FRT PARKING SENSOR WIRING HARNESS ?	1	135.20	-5	128.44	128.44

PARTS TOTAL : 8,464.92

SPECIAL NETT ITEMS

1 FRONT NUMBER PLATE WITH CASING 1 / MIS 35.00

PARTS TOTAL: 35.00

SUB-TOTAL : 8,499.92

GST @ 7% for \$ 8,499.92 594.99

GRAND TOTAL (\$\$) : 9,094.91

FUSO

AIRMAN.

bisSAFE
STAR

SOCOTEC

ISO 9001

Accredited
Certification
SAC
Body
08-1010-02

ESTIMATE

Date	: 16/08/2022	Reg No	: SKG3131T
To	: INDIA INTERNATIONAL INSURANCE PTE LTD	Model	: B.M.W. / 428I CONVERTIBLE AT D/AB HID NAV HUD
Attn.	:	Chassis No	: WBA3V32080J993445
Office / Mobile	:	Engine No	: A7850806N20B20A
Email Address	:	Quotation No.	: 162296
		Ref. No.	: GBE/SVC/SALES-HQ/218-1408
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 14/08/2022
Attn.	: CATHERINECHONGKL	Policy No.	: DMPCSNW00236892100
Office / Mobile	:	Claim Type	: TP CLAIM - INDIA INTERNATIONAL INSURANCE
Email / Fax No.	: CatherineChongKL@goldbell.com.sg	Workshop	: 8 TUAS AVE 18

LABOUR CHARGES

1	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC	300	1500.00
2	TO CHECK FOR AND RECTIFY WIRING FAULTS, TO CONDUCT DIAGNOSTICS CHECK	100	180.00
3	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC	250	900.00

LABOUR TOTAL :	2,580.00
SUB-TOTAL :	11,079.92
GST @ 7% for \$ 11,079.92	775.59
GRAND TOTAL (\$):	11,855.51



GOLDBELL ENGINEERING

Industrial Vehicles. Financial Services.
41,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3676
Finance: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500
Website: www.goldbell.com.sg
Co Reg No: 198003963G

Page 3 / 3

ESTIMATE

Date	: 16/08/2022	Reg No	: SKG3131T
To	: INDIA INTERNATIONAL INSURANCE PTE LTD	Model	: B.M.W. / 428I CONVERTIBLE AT D/AB HID NAV HUD
Attn.	:	Chassis No	: WBA3V32080J993445
Office / Mobile	:	Engine No	: A7850806N20B20A
Email Address	:	Quotation No.	: 162296
		Ref. No.	: GBE/SVC/SALES-HQ/218-1408
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 14/08/2022
Attn.	: CATHERINECHONGKL	Policy No.	: DMPCSNW00236892100
Office / Mobile	:	Claim Type	: TP CLAIM - INDIA INTERNATIONAL INSURANCE
Email / Fax No.	: CatherineChongKL@goldbell.com.sg	Workshop	: 8 TUAS AVE 18

PREPARED BY : CATHERINECHONGKL

DATE / TIME :

SURVEYOR :

MOBILE NO :

OFFICE FAX NO :

EMAIL ADDRESS :

EXCESS AMOUNT :

REPAIR TYPE :

AUTHORISATION :

RE-SURVEY :

NO. OF DAYS :

REMARKS :

LRK Auto Consultants hence notify
the Repaire of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company
Acknowledged by Repaire
Signature:
Date:

FUSO

AIRMAN.

bizSAFE
STAR

