SS. NC. BY: CHYMC	ASSIGNMENT
rom = Date:	
stir x 2 ti Cost	Type: M.Car/M.Cycle/Bus/Van/Lorry/Taxi/Prime Mover/
DI THI WS/TP RES/OD RES/EVA/INV/MV	Truck/Trailer or
o In sport Vehicle No: SKW STUSY	Make: Valkswasen JETTAI-YTELH cc 1390
t Worthop m/s ELITE ANNO MUTINE	Colour NAITE A/C: Insured 1 Std / MI 143
280, bronzamy Intokes Hui-	Sp. Reading 84096 T/Radio: Insured / Std / NI / NA
nsured A/S	Eng/No:
relicy N.	CNO: WVW ZZZ/6ZFM 004 828
Claimes lo.	Gen. Cond: Good / Pair Poor / Burnt
Sum insred: Excess: (W)	Steering: Inorder / Jammed / Leaked / Burnt or
(Client Record)	Brake: Norder / Jammed / Leaked / Burnt or
viake of Veh:	Modi: Nil /S/Rim / STD A/Rim or
	Tyre Size: F: 225/40ZR18
(PolicyCondition)	R: C.
Remark The veh had commenced its N/S	O/S BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or
Ball or Narket Value: 41K	Front Rear
IDAC Acident Rport: Consistent? : Yes or No	R/Bal. 6 mm R/Bal. 6 mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. C mm L/Bal. C mm
Est Repirs: days Res.: Yes or No	D.O.A. 09/08/22 D.O.L. 16/08/22
Lum Sum: % 3 Val.: Yes or No	Survey held at FLITE AMOMOTIVE
CA / (REV) REP. / 24 HRS	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: 1	그러지 그는 그는 아니라 함께 되어 얼마를 살아가 살아서 되었다. 아이를 하고 하고 있다고 있다면 하네 사람들이 하는 것이 모든 사람들이 되었다. 그는 그는 그는 그 그는 그를 다 되었다.
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
REPAIR LIMIT- 16K	
	보스는 11을 통해 보면 이 중에 기계 시간에 되었다. 그 그 것이 없는 것이 되었다. 11일 - 12일 기계 (1997년 1일 대표를 하고 있는 1일 기계
hala/True Sta Bassing	
Preli. Report	Days Of Repair:
: Final Report	Resurvey No. of Trip: Survey Fee:
late/Time. File Return to?	[14] 12] [12] [12] [12] [12] [12] [12] [12]
Ad	d Fee: Site Insp. (\$): S+PS St
4 m	Tabanian 16
있습니다. 없이 하는데 그의 전하는 것 하는 모양됐다면서	THE PROPERTY OF THE PROPERTY O
eport Format : ump Sum / I.B.I: (\$: Tech, Invs (\$) Photos

un immange, which was the contract of the

TOTAL

ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17, Harvest @ Woodlands Singapore 757322
Tel: 6339 7378 Fax: 6339 7475

Vehicle Number: SKW5925Y

Vehicle Model: VOLKSWAGEN JETTA

Chassis Number: WVWZZZ16ZFM001828

Estimated Repair Cost

S/N	Parts Description	Qty		Cost Price
1	BONNET A	1	\$	700.00
	BONNET HINGES (LH & RH)	2	\$	240.00
2	BONNET STAND \	1 -	\$	60.00
	BONNET STAND CLIP X	1	\$	5.00
4	BONNET STAND CEIT / S	1	\$	200.00
5	FRONT BUMPER	1	\$	1050.00
6	EDON'T DUMPED CLIPS 16	10	\$	30.00
7	FRONT BUMPER RETAINER (LH & RH) LH? KH-X	11/2	\$	80.00
8	FRONT BUMPER REINFORCEMENT 7.	1	\$	500.00
9	FRONT BUMPER INNER SPONGE 7.	1	\$	90.00
10	FRONT BUMPER LOWER GRILLE	1	\$	250.00
11		1	\$	500.00
12	FRONT BUMPER LOWER LIP X FOG LAMP (LH & RH) X	2	\$	500.00
13	FOG LAMP COVER (LH & RH)	2	\$	240.00
14	FRONT GRILLE CM	1	\$	450.00
15	FRONT GRILLE LOGOMIS	1	\$	120.00
16	FRONT GRILLE CLIPS 2	10	\$	30.00
17	SUPPORT PANEL CA		\$	800.00
18	SUPPORT PANEL TOP GARNISH CLIPS	10	\$	30.00
19 20	21 × 11 11 - 10 1		\$	1000.00
21	HEADLAMP (LH & RH) KH KH LH - b+/KH-X		\$	240.00
22	HEADLAMP (LH & RH) KH-Y-LH-SH/KH-X FRONT FENDER (LH & RH) RH-Y-LH-SH/LH-SH- FRONT LHS SPLASH SHIELD X		\$	960.00
23	FRONT LHS SPLASH SHIELD X	$ \frac{1}{1}$	\$	150.00
24		10	\$	30.00
25		2	\$	240.00
26		1.0	\$	550.00
27	MADIATION , 7	1	\$	480.00
28		1		200.00
29		1	n* \$1 4	90.00
25	Spare Parts p	rice	\$	9815.00
	Cost Price +1		\$	981.50
	Cost Thee		\$	10,796.50
S/N	Special Nett Items:	Qty		303 , 1
1	FRONT NUMBER PLATE WITH HOLDER	1SET	\$	60.00 35
•				

60.00

10856.50

\$

Special Nett Total

Spare Part's Total Price

ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17, Harvest @ Woodlands Singapore 757322
Tel: 6339 7378 Fax: 6339 7475

Vehicle Number: SKW5925Y

Vehicle Model :VOLKSWAGEN JETTA Chassis Number : WVWZZZ16ZFM001828

		tions Charges		
/N	Labour Descriptions	\$	1800.00	
1	LABOUR CHARGES TO REMOVE & INSTALL FRONT END ATTACHMENTS & FITTINGS TO ENABLE REPAIRS; TO REPLACE DAMAGED PARTS AS LISTED ABOVE.	*	1000	
2	TO SPRAY PAINTING ON: BONNET, FRONT BUMPER, FRONT BOTH FENDER, SUPPORT PANEL, FRONT LHS DOOR, "A" PILLAR (LH& RH)	\$	1890.00 1000	
3	TO REMOVE & INSTALL A/C CONDENSER & RECEIVER DRYER, TO ENABLE REPAIRS, TO VACUMM & CHARGE UP GAS.	\$	150.00	
4	TO CHECK DIAGNOSE & REMOVE FAULT CODES AFTER ACCIDENT REPAIRS.	\$	280.00 (C	
5	TO CHECK ELECTRICAL WIRINGS & HEADLIGHTS FUNCTION, INCLUSIVE FOCUS HEADLIGHTS.	\$	150.00 3	
ϵ	TO REMOVE & INSTALL RADIATOR & HOSES TO ENABLE REPAIR. INCLUDING PRESSURIZE COOLING SYSTEM.	\$	150.00 6	
,	7 TOWING FEES receipt?	\$	60.00 -	
	Labour Tota	1 \$	4390.00	
	Parts & Labour Tota	1 \$	15246.50	
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged gart(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:	days 120 1220 1255:	1620 600 Uzvepáir	
	Re	UKI	Or mair	

SE0K228A0001 / Elite Automotive Pte Ltd ENTRY DATE & TIME: 10/08/2022 16:05 (SGT) SUBMITTED BY: Lim Wee Kiang Ivan VERSION: 1 (10/08/2022 16:05 (SGT))



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Actual Driver

- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission

Reported by

Date of Accident

Exact Location of Accident

Additional Location Information

Country/State of Loss

10/08/2022 16:05 (SGT)

Both

09/08/2022 13:00 (SGT)

Singapore

NORTH SELETAR LINK GOING INTO PUNGGOL WAY

Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SKW5925Y

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner

NRIC No

Email Address

Mobile Phone No

Alternative Phone No

No

S R SURRIYA

SXXXX269E

surriya96@gmail.com

(Phone) +65-81902414

VEHICLE PARTICULARS

Manufacturer

Model

Variant

Exact purpose for which vehicle was being used at time of

Are you claiming under your own insurance policy for repair to your vehicle?

Vehicle Category

Transmission

CC

Volkswagen

Jetta

Private use

Yes

Private car

Auto

1390

INSURANCE COMPANY

Name of Insurance Company

Policy Number / Cover Note Number

Allianz Insurance Singapore Pte. Ltd. SP2001845257-01

DRIVER

Name of Driver NRIC No

Date Of Birth Occupation

S R SURRIYA SXXXX269E 30/08/1996 Outdoor

Accident report SE0K228A0001

Date Of Driving Pass 16/07/2020 Driving experience 2 YEARS AND 1 MONTH Gender Male Mobile Number (Phone) +65-81902414 Alt. Phone Number **Fmail Address** surriya96@gmail.com Address BLK 405B NORTHSHORE DRIVE Address complement #06-120 Postcode 822405 Is the driver the policyholder? Yes If No. Relationship of the Driver with the Insured Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Head to Rear Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement PASSENGER 1 Name NISHTA SIVA KUMAR Gender Female PASSENGER 2 Name HIRAN SURRIYA Gender Male DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT REFER TO ATTACHED. ATTACHMENT(S)

DETAILS OF OTHER VEHICLE PROPERTY 1

Yes

No

Are accident photos available for attachment?

Was there any video captured by Car Camera?

Vehicle Registration Number	SNB5990H
Vehicle Manufacturer	- 10
Vehicle Model	-
Vehicle Variant	- 7,0
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	(Phone) +65-98311319
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	•
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to spreed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies a not as admission of policy hability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 5. The report will be forwarded by the insurers of the GIA Records Management Ceptre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of the report will for a fee be made available upon application by interested parties.
- By the Jodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of
 the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect; use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the last sets' lawyers/ aw firms, the Mogetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) information.
 - (i) processing manaling and/or dealing with my claims including the settlement of the claims and any necessary investigation in lating to the claims:
 - (ii) investigating the accident and, ar my daims:
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering myidalins including the mailing of correspondence, statements, involves, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of involopes/mail packages); and/or
 - (v) complying with applicable lawin administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use; disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assistin evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court pricers.

Palicyholder's Signature

Date & Time:

Driver's Signature (If driver is not the policyholder) Date & Time:

Reporting Centre Personnel's Signature

NRIC/FIN No.:



vehicle A: skw squsy

B: SNB s990-1

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Last SNB SHOH pure brake infront of me I could not stop in time and rearrided	i uas	travelling at Borth solder Lind	le to thin into punggot may. A brewn velve number >
	lot e	SNB 54904 jam broke introm	et the I cond tool
	TAKE.		
	-		
	0-1-		
	7	1,410	
		The state of the s	
	Park I		
			38
	1		
		The second secon	
	A 17		
	- 11	The state of the s	
			The state of the s
		2 A 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 8
			Sec. 10.01

DECLARATION

I/We declare the foregoing particulars are true in every respect

Gu-Policyholder's Signature

Date & Time:

Driver's Signature (If driver is not the policyholder) Date & Time.

Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

Volkswagen Jetta 1.4A TSI Highline

Overview Fina	ncial Accessories Sim	nilar Research	Photos Map
Price	\$39,000		
Depreciation ⑦	\$13,300 /yr View models with similar depre	Reg Date	20-Mar-2015 (2yrs 7mths 2days COE left)
Mileage	106,000 km (14.3k /yr)	Manufactured ⑦	2014
Road Tax ⑦	\$620 /yr	Transmission	Auto
Dereg Value 🕜	\$20,300 as of today (change)	OMV ⑦	\$19,152
COE ②	\$57,199	ARF ⑦	\$9,152
Engine Cap	1,390 cc	Power	90.0 kW (120 bhp)
Curb Weight ⑦	1,417 kg	No. of Owners ⑦	1
Type of Vehicle	Mid-Sized Sedan		

, Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

The information contained herein is correct as at 10 Aug 2022

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	269E
Vehicle Details	100
Vehicle No.:	SKW5925Y
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Aug 2022
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	JETTA GP 1.4 TSI 90 A/T HL 1634G5
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	CAXF17162
Chassis No.:	WVWZZZ16ZFM001828
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$19,614.00
Original Registration Date:	29 May 2015
First Registration Date:	29 May 2015
Transfer Count:	2
Actual ARF Paid: Intended PARF Rebate Details	\$9,614.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 May 2025
PARF Rebate Amount: Intended COE Rebate Details	\$5,768.00
COE Expiry Date:	28 May 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$66,590.00
COE Rebate Amount:	\$18,634.00
Total Rebate Amount:	\$24,402.00

~ .