

305525863 Our Job Ref No 🚡 ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969 27.08.2022 **FINALIZATION FORM** LKK Fax: **TAUFIKH** Attn 💈 Vehicle Reg No. : SH7760B 10.08.2022 The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-Ζ The repair job shall bill to: **NTUC GBC5849X** 2. The finalized amount shall be: Spare Parts after List discount (b) Labour Charges Total for Part-By-Part Repair Cost (c.) Lumpsum Repair (if applicable) Total for Lumpsum repair cost after Less: Final Lumpsum Repair cost \$6,450.00 3. Estimated normal period for repairs: 6 working days. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 4. 7 working days 5. Thank you for your assistance: We confirm the estimates and finalized amount Signature: Signature: Name : CHIANG Name TAUFIKH 28/9/22 62148314 Tel Date 65468156 Fax For Official Use Only Document Confirm By Item Amount Remarks Attached (Signature) Yes or No 1. Rental Rate P/Day YES 2. Loss of Income Paid Ν 3. Survey Fees 4. LTA Search Fee \$7.49/\$2.00 YES 5. Medical Fees (on behalf of driver, if applicable) 6 Overrun Remarks: