

ASS. REC. BY: Taughin

REF:

INC

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Chang Vehicle: IN / OUTVeh No: SH7760B Yr Regn: 2016 May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai 140 C.C. 1685Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RMH4LB414MG4087920Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westeche

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 10/8/22Survey held at Confert Bay

Des. of Damages: Frt / Rear / O/S / N/S / U/C + Rooftop: or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Battery weak

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Rep. Format: _____

Lump Sum / L.B. / C

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

REPAIR ESTIMATE*

10.08.2022

MODEL **HYU- I40**

CHIANG/NTUC

- * To provide fair book value
- * To check upper limit of fair

Date/Time: 10.08.2022 08:27

Page : 1

eam: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4522866

JC N05525863

USTOMER

3/MS COMFORT TRANSPORTATION PTE LTD

USTOMER NO. 7010045

ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717

L. (R) 65508755 (O)

(P)

SCOUNT CARD NO.

REGN NO.

SH 7760B

MILEAGE

MAKE

HYUNDAI

FUEL

E.....1/2.....F

MODEL

I-40

08.08.2022 08:36

DATE/TIME IN

YR OF MANU.

12.05.2016

TARGET DATE

CHASSIS CODE

KMHLB41UMGU087920

COMPLETION DATE/TIME:

JOB DESCRIPTION


ccident Date: 10.08.2022

ATURE: TP/3P 31.07.2022

/NO

LABOR CODE

DESCRIPTION



HECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

nowledgement Slip

Exit Pass

3:

o.:

le No.: SH 7760B

CHIANG

Vehicle No.:

SH 7760B

3 of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard