

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





AUTOMOBILE INSPECTION REPORT						
INCOME INSURANCE LTD			Ref:	NS/INC22007799/Tvce2		
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	05-10-2022		
4				INC4		
1.	Policy Particulars :- THIRD PARTY CLAIM Insured Veh. SJR 6140B Veh. Inspected SHA 7950L					
		3JR 0140B		<u> </u>	0.00	
	Policy No.	MT/1184114-002		age (\$)	0.00	
	Assign From	10171104114-002	Exces	,	11/08/2022	
0						
2.	Vehicle Particulars & Condition					
	Make & Model	HYUNDAI IONIQ HIDDEN	C.C	4 Don	1580 2019	
	Engine No. Chassis No.	KMHC851CVLU187210	Year o		BLUE	
	Odometer	258645			IN ORDER	
	Brakes	IN ORDER	Steerii		NIL NIL	
	General	GOOD	Wiodin	Cation	IVIL	
3.	1000000					
J.	Conditions of Tyres Size Make Balance					
	R/H Front Tyre	195/65 R15	WEST	ΔKE	6 mm	
	L/H Front Tyre	195/65 R15	WEST		6 mm	
	R/H Rear Tyre	195/65 R15	WEST		6 mm	
	L/H Rear Tyre	195/65 R15	WEST		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.						
	Accident Date					
	Survey held at	COMFORTDELGRO ENGINEER	RING PTE LTD			
		59 LOYANG DRIVE SINGAPORE 508969				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days					