

## REF:

From: \_\_\_\_\_ Date: \_\_\_\_\_

Veh No: SMK7409Y, Yr Regn: 2017 / April

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Shuttle C.C 1496.

Colour Silver. A/C: Insured / Std / NI / NA

Sp. Reading 71877 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: GK82001658 \*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modif: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60 R15

R: 185/60R15

R: 185/60R15

Front Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. \_\_\_\_\_ D.O.I. 15/08/22

Survey held at HD Perfect!

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

0894

☐ : Prel. Report

**Final Report**

Days Of Repair:

Resurvey No. of Trip:

Transportation:

Add Fee:  : Site Insp (\$

☐ Interview (\$

Tech. inv. (6)

3) Photos

|        |   |
|--------|---|
| Others | 1 |
|--------|---|