

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



AUTOMOBILE INSPECTION REPORT					
INCOME INSURANCE LTD			Ref:	NS/INC22007806/Tqcm4	
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	25-10-2022 INC4	
1.	Policy Particulars :- THIRD PARTY CLAIM				
1.				nspected	SHC 1387S
	Policy No.			age (\$)	0.00
	Claim No.	MT/1184068-002	Exces	<u> </u>	0.00
	Assign From		Assign	,	12/08/2022
2.					
	Make & Model	HYUNDAI IONIQ	c.c	Condition	1580
	Engine No.	HIDDEN	Year o	f Rea.	2019
	Chassis No.	KMHC851CVLU188049	Colou		BLUE
	Odometer	331810	Steerii	ng	IN ORDER
	Brakes	IN ORDER	Modifi		NIL
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	195/65 R15	WEST	LAKE	6 mm
	L/H Front Tyre	195/65 R15	WEST	LAKE	6 mm
	R/H Rear Tyre	195/65 R15	WEST	LAKE	6 mm
	L/H Rear Tyre	195/65 R15	WEST	LAKE	6 mm
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.				
	DAMAGES SEE DETAILS.				
5.					
	Accident Date	11/08/2022		tion Date	12/08/2022
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD			
		59 LOYANG DRIVE SINGAPORE 508969			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	D. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days				