

ASS. REC:BY: Taught

REF:

INC
ASSIGNMENT

From: _____ Date: _____

Estimated cost: _____

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SNC1387S Yr Regn: 249, Nov

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Hyundai C.C. 1580Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 551870 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMA085102408049

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: NH / S/Rim / STD A/Rim or _____

Tyre Size: F: 195/65R15R: 2

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westerlund

Front Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. D.O.I. 12/8/22Survey held at Comfit Lorry

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rt + N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Rep. Format: _____

Lump Sum / I.B.A. (\$) _____

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHC1387S

Date: 12.08.2022

Make : HYUNDAI

Insurance: NTUC

Model : IONIQ(G3)

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	FRT BUMPER COVER			\$ 481.10
10	FRT BUMPER CLIPS			\$ 22.00
1	FRT BUMPER SIDE BRACKET LH			\$ 28.00
1	FRT BUMPER CENTRE MOULDING UPPER			\$ 368.50
1	HEADLAMP LH			\$ 2,110.30
1	FRT BUMPER SIDE MOULDING LH			\$ 93.45
1	DAY LIGHT LH			\$ 642.50
1	FRT FENDER LH			\$ 588.80
1	EMBLEM - BLUE DRIVE LH			\$ 26.60
1	FRT WHEEL HUB CAP LH			\$ 346.40
	SUB TOTAL			\$ 4,707.65
	LESS 20%			\$ 948.13
	DISCOUNTED TOTAL			\$ 3,759.52
	 FRT FENDER ADVERTISEMENT LH			\$ 100.00
				\$ 100.00 nett
	Labour Charge			
	PANEL BEATING			\$ 750.00
	SPRAY PAINTING CHARGE			\$ 600.00
	TUFF KOTE			\$ 60.00
	CHECK LIGHTING / WIRING			\$ 60.00
	TOTAL LABOUR			\$ 1,470.00
	ESTIMATE TOTAL			\$ 5,329.52

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Paym 97495749
 up 12/08/22 04pm
 1/8 hrs my after repair
 further 11 hrs work on
 2-3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by: Repairer

Signature:

Date:

Date/Time: 12.08.2022 15:43

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4525206

JC No: 905526307

CUSTOMER

R/MS COMFORT TRANSPORTATION PTE LTD

CUSTOMER NO. 7010045

ADDRESS 383 SIN MING DRIVE

Singapore SINGAPORE 575717

TEL. (R) 65508755

(O)

(P)

SCOUT CARD NO.

REGN NO.:

SHC1387S

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G3)

DATE/TIME IN

11.08.2022 22:15

YR OF MANU.

07.11.2019

TARGET DATE

CHASSIS CODE

KMHC851CVLU188049

COMPLETION DATE/TIME:

JOB DESCRIPTION


Accident Date: 11.08.2022

NATURE: 3P 11.08.2022

/NO

LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

No.: SHC1387S

YY

Vehicle No.:

SHC1387S

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard