

AGS. REC BY: Taufik

REF:

NS/ INC. 22007808/Tvc

ASSIGNMENT

From: _____ Date: _____

Estimated cost: _____

OD / TP / IS / TP RES / OD RES / EVA / INV / MV

To Inspect/Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SLF 3497G

Policy No. _____

Claims No. MT/1183978-003

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Chang

Vehicle: IN / OUT

Veh No: SMD 4350Y Yr Regn: 2019 Dec

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai C.C. 1580

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 435625 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KM40851CVL4190529

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: 17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 11/8/2022 D.O.I. 12/8/22

Survey held at Comfort Lodge

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

29/9/22 Taufikh informed LS \$2750 (Red 2333.68, 45%)

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 29/9/22-typist

Report Format: TP

Lump Sum / H.B. / : \$2750

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHD4350Y

DATE 11.08.2022

MAKE REG.19.12.2019

MODEL : HYU IONIQ G2

CHIANG/NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT BUMPER BRACKET RH			\$35.00
1	FRONT BUMPER			\$481.10
1	FRONT BUMPER CENTRE UPPER MOULDING			\$368.50
1	FRONT BUMPER GRILLE RH			\$186.50
1	FRONT DAY LIGHT RH			\$642.50
1	FRONT FENDR SHIELD RH			\$164.70
1	FRONT FENDER EMBLEM			\$26.60
1	HEAD LAMP RH			\$2,110.30
1	FRONT WHEEL COVER			\$364.40
	SUB TOTAL			\$4,379.60
	20.00% DISCOUNTED TOTAL			\$875.92
				\$3,503.68
1	FRONT FENDER ADVERTISEMENT			\$100.00
				\$100.00
	Labour Charge			
	Panel Beating			\$700.00
	Spray Paint			\$600.00
	Reset Wheel alignment			\$60.00
	Check lighting			\$60.00
	Towing Fee			\$60.00
	TOTAL LABOUR			\$1,480.00
	ESTIMATE TOTAL			\$5,083.68
<i>Transfer 97495749</i> <i>WR 12/8/22 04pm</i> <i>C/S Rising after repair</i> <i>2-3 days</i> <i>transfer to insurance</i>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hence notify the Repairer of the following:

- To display proposed costs to the repairer
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 12.08.2022 09:07

Page : 1

eam: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 4525110

JC NO 305526209

USTOMER

NAME COMFORT TRANSPORTATION PTE LTD

CUSTOMER NO. 7010045

ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717

TEL (R) 65508755

(O)

(P)

SCOUT CARD NO.

REGN NO.:

SHD4350Y

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G3)

DATE/TIME IN 11.08.2022 16:10

YR OF MANU.

19.12.2019

TARGET DATE

CHASSIS CODE

KMHC851CVLU190329

COMPLETION DATE/TIME:

JOB DESCRIPTION


Accident Date: 11.08.2022

ATURE: 3P 11.08.2022

/NO

LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

BY:

DATE:

Vehicle No.: SHD4350Y

CHIANG

Vehicle No.:

SHD4350Y

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard