

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 15.08.2022

Time: 08:22:36

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305526371
 REGN NO : SHA5630Z
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 03.09.2018
 DATE/TIME IN : 12.08.2022 15:25
 ACCIDENT DATE : 11.08.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 03-01-0104-2137-G REAR WHEEL CAP RH / 1 346.40 20.00 277.12

SUB-TOTAL : 277.12

JOB NATURE

0000 PB	PANEL BEATING-Rear Fender ^{RH} Etc	800.00	350
0001 SP	SPRAYPAINT-Rear Bumper Etc	600.00	500
0002 20-00	TUFF COAT ON AFFECTED PARTS.	30.00	X AN
0003 20-05	Rear Fender Adv.Sticker RH/LH / MC	200.00	/

SUB-TOTAL : 1,630.00

TOTAL : 1,907.12

MVA NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO

SURVEYOR NAME & SIGNATURE

DATE :

Link

*2 Day r.
4/5
Sms Qs ap
15/8/22
4pm*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey the repair work
- To display the repair work
- Parts provided on "as is" basis
- Third party liability
- No illegal work
- Supplemental work is subject to prior approval and

Acknowledged by the Repairer

Signed by the Repairer

Dated