National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

AUTOMOBILE INSPECTION REPORT

INCOME INSURANCE LTD

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE 189556

Ref: NS/INC22007828/Gvcm4

Date: 07-10-2022

Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

	Insured Veh.	GBH 4558R	**Veh. Inspected**	SHC 1810L
	Policy No.		**Coverage ($)**	0.00
	Claim No.	MT/1186769-001	**Excess ($)**	0.00
	Assign From		**Assign Date**	15/08/2022

2. Vehicle Particulars & Condition

	Make & Model	HYUNDAI AE IONIQ HEV 1.6	**c.c**	1580
	Engine No.	HIDDEN	**Year of Reg.**	2018
	Chassis No.	KMHC851CVKU107536	**Colour**	BLUE
	Odometer	-	**Steering**	IN ORDER
	Brakes	IN ORDER	**Modification**	NIL
	General	GOOD		

3. Conditions of Tyres

		Size	**Make**	**Balance**
	R/H Front Tyre	195/65 R15	WEST LAKE	6 mm
	L/H Front Tyre	195/65 R15	WEST LAKE	6 mm
	R/H Rear Tyre	195/65 R15	WEST LAKE	6 mm
	L/H Rear Tyre	195/65 R15	WEST LAKE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION & O/S BODY.

DAMAGES SEE DETAILS.

5. General Information

	Accident Date	12/08/2022	**Inspection Date**	15/08/2022
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **2 Working Days**