

**COMFORTDELGRO
ENGINEERING**

Our Job Ref No : 305526417
Date 17.08.22


ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK Fax : _____
Attn : Mr GUO QIANG
Vehicle Reg No. SHC2528X Date of Accident : 14.08.22

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- FBS3078H
2. The finalized amount shall be:
 - (a) Spare Parts after List discount _____
 - (b) Labour Charges _____
 - Total for Part-By-Part Repair Cost** _____
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% \$1,500.00
Final Lumpsum Repair cost _____
3. Estimated normal period for repairs: 2 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance. We confirm the estimates and finalized amount

Signature : 
Name : JUMANI
Tel : 62148315
Fax : 65468156

Signature : _____
Name : GUO QIANG
Date : _____

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	----	NO		
3. Survey Fees	----	---		
LTA Search Fee	\$7.49 / \$2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

VEHICLE NO. : SHC2528X

TYPE OF INS. : NTUC

JOB CARD NO. 305526417

SURVEY BY : LKK- GUO QIANG

ACC.DATE 14.08.22

DATE :

SUPPLEMENTARY OF PARTS AND LABOUR COSTS			
DESCRIPTION	QTY	ESTIMATE	REMARKS
RERA BUMPER LOWER MLDG	1	\$155.00	LIST
CHECK ITEM			
LABOUR			
TOTAL:			JUMANI