

AGS. REC3Y:

REF:

CS/CT122007837/Tgy3

ASSIGNMENT

From: _____ Date: _____

Estimated lost: _____

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To Inspec/Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 8110K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNA87164 Yr Regn: 2021 July

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Kia Cerato C.C. 1591Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 9800 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNAF3416MM*5107124Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Kumho

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 17/8/22Survey held at Biprest

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report1) _____
Date/Time, File Return to?☐ : Final Report

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS, SI _____

Photos _____

Others _____

TOTAL

Report Format: _____

Lump Sum / I.B.L. (\$) _____

Bifrost Auto Pte Ltd

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875
Tel: 93290237 Email: claims_rar@bifrostauto.com

SJE : _____
Date of Survey : _____
Date of ReSurvey: _____
Contacts : _____

Vehicle Nos : **SNA 8716U**
Made : Kia
Model : Cerato 1.6(A) EX
Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Rear Bootlid	1	\$ 1,491.00	\$ <input checked="" type="checkbox"/> 1,491.00
2	Rear Bootlid Emblem	1	\$ 32.00	\$ <input checked="" type="checkbox"/> 32.00
3	Rear Bootlid "Cerato" Emblem	1	\$ 28.00	\$ <input checked="" type="checkbox"/> 28.00
4	Rear Bootlid Inner Trim	1	\$ 202.00	\$ <input checked="" type="checkbox"/> 202.00
5	Rear Bootlid Weatherstrip	1	\$ 110.00	\$ <input checked="" type="checkbox"/> 110.00
6	Rear Bootlid Lock	1	\$ 112.00	\$ <input checked="" type="checkbox"/> 112.00
7	Rear Bootlid Lock Catch	1	\$ 40.00	\$ <input checked="" type="checkbox"/> 40.00
8	Rear Bootlid Taillamp Centre	1	\$ 690.00	\$ <input checked="" type="checkbox"/> 690.00
9	Rear Bootlid Taillamp RH	1	\$ 608.00	\$ <input checked="" type="checkbox"/> 608.00
10	Rear Bootlid Taillamp LH	1	\$ 608.00	\$ <input checked="" type="checkbox"/> 608.00
11	Rear Taillamp Assembly RH	1	\$ 675.00	\$ <input checked="" type="checkbox"/> 675.00
12	Rear Taillamp Assembly LH	1	\$ 675.00	\$ <input checked="" type="checkbox"/> 675.00
13	Rear Bumper	1	\$ 651.00	\$ <input checked="" type="checkbox"/> 651.00
14	Rear Bumper Lower Lip	1	\$ 241.00	\$ <input checked="" type="checkbox"/> 241.00
15	Rear Bumper Side Bracket RH	1	\$ 31.00	\$ <input checked="" type="checkbox"/> 31.00
16	Rear Bumper Side Bracket LH	1	\$ 25.00	\$ <input checked="" type="checkbox"/> 25.00
17	Rear Bumper Under Cover	1	\$ 33.00	\$ <input checked="" type="checkbox"/> 33.00
18	Rear Bumper Reflector Garnish RH	1	\$ 19.00	\$ <input checked="" type="checkbox"/> 19.00
19	Rear Bumper Reflector RH	1	\$ 201.00	\$ <input checked="" type="checkbox"/> 201.00
20	Rear Bumper Reflector Garnish LH	1	\$ 19.00	\$ <input checked="" type="checkbox"/> 19.00
21	Rear Bumper Reflector LH	1	\$ 201.00	\$ <input checked="" type="checkbox"/> 201.00
22	Rear Bumper Beam	1	\$ 318.00	\$ <input checked="" type="checkbox"/> 318.00
23	Rear Bumper Beam Bracket Upper RH	1	\$ 9.00	\$ <input checked="" type="checkbox"/> 9.00
24	Rear Bumper Beam Bracket Upper LH	1	\$ 9.00	\$ <input checked="" type="checkbox"/> 9.00
25	Rear Bumper Beam Bracket Lower RH	1	\$ 6.00	\$ <input checked="" type="checkbox"/> 6.00
26	Rear Bumper Beam Bracket Lower LH	1	\$ 6.00	\$ <input checked="" type="checkbox"/> 6.00
27	Rear Bumper Beam Bracket Lower	1	\$ 6.00	\$ <input checked="" type="checkbox"/> 6.00
28	Rear Bumper Beam Stay RH	1	\$ 65.00	\$ <input checked="" type="checkbox"/> 65.00
29	Rear Bumper Beam Stay LH	1	\$ 65.00	\$ <input checked="" type="checkbox"/> 65.00
30	Rear Bumper Reverse Sensor	2	\$ 163.00	\$ <input checked="" type="checkbox"/> 326.00
31	Rear Bumper Reverse Sensor Wire Harness	1	\$ 207.00	\$ <input checked="" type="checkbox"/> 207.00
32	Rear End Panel	1	\$ 324.00	\$ <input checked="" type="checkbox"/> 324.00

33	Rear End Panel Top Garnish	1	\$ 41.00	\$ X	41.00
34	Rear Spare Tyre Panel Top Board	1	\$ 290.00	\$ X	290.00
35	Rear Fender RH	1	\$ 1,349.00	\$ X	1,349.00
36	Rear Fender LH	1	\$ 1,349.00	\$ X	1,349.00
37	Rear Fender Inner Trim RH	1	\$ 374.00	\$ X	374.00
38	Rear Fender Inner Trim LH	1	\$ 374.00	\$ X	374.00
39	Rear Exhaust Muffler	1	\$ 757.00	\$ X	757.00
40	Rear Exhaust Mounting	2	\$ 45.00	\$ X	90.00
41	Rear Exhaust Heat Shield	1	\$ 68.00	\$ X	68.00
				Parts Sub Total :	\$ 12,725.00
				10% Discount	\$ 1,272.50
				PARTS TOTAL :	\$ 11,452.50

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Rear Number Plate	1	\$ 50.00	\$ X 50.00
2	Rear Bumper Clips - Set	1	\$ 50.00	\$ 30 net 50.00
3	Rear Bootlid Inner Trim Clips - Set	1	\$ 50.00	\$ X 50.00
4	Rear End Panel Top Garnish Clips - Set	1	\$ 50.00	\$ X 50.00
5	Rear Fender Inner Trim Clips RH - Set	1	\$ 50.00	\$ X 50.00
6	Rear Fender Inner Trim Clips LH - Set	1	\$ 50.00	\$ X 50.00
7	Rear Bootlid Sealant	1	\$ 150.00	\$ X 150.00
8	Rear End Panel Sealant	1	\$ 150.00	\$ X 150.00
9	Rear Fender RH Sealant	1	\$ 150.00	\$ X 150.00
10	Rear Fender LH Sealant	1	\$ 150.00	\$ X 150.00
11	Rear Windscreen Glass Sealant	1	\$ 150.00	\$ X 150.00
12	Rear Bootlid C&C Emblem	1	\$ 50.00	\$ X 50.00
13	Kia Cerato Bodykit - Set	1	\$ 1,721.00	\$ X 1,721.00
14	Rear Bootlid Reverse Camera	1	\$ 550.00	\$ X 550.00
SPECIAL NETT TOTAL :				\$ 3,371.00

Nos.	LABOUR	TOTAL S\$
1	To Panel Beat, Remove & Refix Parts	\$ 2300 2,200.00
2	To Spray Paint Affected Areas	\$ 300 1,600.00
3	Wiring & Bulb Check	\$ X 100.00
4	To Transfer Rear Bootlid Mechanism	\$ X 150.00
5	To Remove & Refix Rear Windscreen Glass	\$ X 150.00
6	To Remove & Refix Rear Bumper Reverse Sensor	\$ 30 120.00
7	To Remove & Refix Rear Bootlid Reverse Camera	\$ X 150.00
8	To Remove & Refix Rear Exhaust Pipe to facilitate repairs	\$ X 150.00
9	To Remove & Refix Fuel Tank to facilitate repairs	\$ X 250.00
10	To apply anti rust on affected parts	\$ X 180.00
11	To Remove & Refix Interior Upholstry to facilitate repairs	\$ 150 150.00
12	To Conduct Water Leak Test	\$ X 100.00
13	To Send for Diagnostic and Reset Control Unit. Programming & Calibration	\$ X 480.00
LABOUR TOTAL :		\$ 5,780.00

Tanjinh 92495749
 12/11/22 @ 3pm - 3 days
 To check consistency of accident
 To check part price.
 4/3 Rising after repair
 for form C/Mount...
 Doc

PARTS TOTAL :	\$	11,452.50
SPECIAL NETT TOTAL :	\$	3,371.00
LABOUR TOTAL :	\$	5,780.00
GRAND TOTAL :	\$	20,603.50

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	688F

Vehicle Details

Vehicle No.:	SNA8716U
Vehicle to be Exported:	Yes
Intended Deregistration Date:	16 Aug 2022
Vehicle Make:	KIA
Vehicle Model:	CERATO 1.6(A) EX
Primary Colour:	Grey
Manufacturing Year:	2021
Engine No.:	G4FGMH702774
Chassis No.:	KNAF3416MM5107124
Maximum Power Output:	93.8 kW (125 bhp)
Open Market Value:	\$14,478.00
Original Registration Date:	21 Jul 2021
First Registration Date:	21 Jul 2021
Transfer Count:	1
Actual ARF Paid:	\$14,478.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Jul 2031
PARF Rebate Amount:	\$10,858.00

Intended COE Rebate Details

COE Expiry Date:	20 Jul 2031
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,001.00
COE Rebate Amount:	\$36,000.00
Total Rebate Amount:	\$46,858.00

The information contained herein is correct as at 16 Aug 2022

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	12/08/2022 10:55 (SGT)
Reported by	Both
Date of Accident	09/08/2022 17:30 (SGT)
Exact Location of Accident	Marina Gardens Dr, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SNA8716U
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	NG YU SHAO
NRIC No	S9033688F
Email Address	NGYUSHAO@GMAIL.COM
Mobile Phone No	(Phone) +65-97656215
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Kia
Model	Cerato
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1600

INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Policy Number / Cover Note Number	RV00000570046

DRIVER

Name of Driver	NG YU SHAO
NRIC No	S9033688F
Date Of Birth	24/08/1990
Occupation	Indoor

Date Of Driving Pass	18/01/2010
Driving experience	12 YEARS AND 7 MONTHS
Gender	Male
Mobile Number	(Phone) +65-97656215
Alt. Phone Number	-
Email Address	NGYUSHAO@GMAIL.COM
Address	BLK 139B LORONG 1A TOA PAYOH #18-50
Address complement	-
Postcode	312139
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	KHOO LEE KUAN
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

ON THE STATED DATE AND TIME, (SNA8716U) WAS TRAVELLING ALONG MARINA GARDENS DRIVE .AS I WAS QUEUING FOR MY TURN TO GET INTO THE CARPARK. I FELT AN IMPACT FROM MY REAR. I ALIGHTED AND FOUND OUT THAT VEHICLE (SLL4336A) AS HIT ONTO MY VEHICLE REAR.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	NOT AVAILABLE. WITH TP WORKSHOP

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLL4363A
-----------------------------	----------

Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	VEHICLE B
No. Of Passenger (Including Driver)	-