

# COMFORTDELGRO ENGINEERING

Our Job Ref No : 305526418  
Date 18.08.22

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156


## FINALIZATION FORM

To : LKK Fax : \_\_\_\_\_  
Attn : Mr GUO QIANG  
Vehicle Reg No. SHA4307P Date of Accident : 07.08.22

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: INDIA --- SLM1755M
2. The finalized amount shall be:
 

(a) Spare Parts after List discount	<u>\$829.28</u>
(b) Labour Charges	<u>\$651.00</u>
<b>Total for Part-By-Part Repair Cost</b>	<b><u>\$1,480.28</u></b>
(c.) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less: <u>20%</u>	<u>                    </u>
<b>Final Lumpsum Repair cost</b>	<b><u>                    </u></b>
3. Estimated normal period for repairs: 2 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance. We confirm the estimates and finalized amount

Signature :   
Name : JUMANI  
Tel : 62148315  
Fax : 65468156

Signature : \_\_\_\_\_  
Name : GUO QIANG  
Date : \_\_\_\_\_

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	----	NO		
3. Survey Fees	----	---		
LTA Search Fee	\$7.49 / \$2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

\_\_\_\_\_

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS : COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305526418  
 REGN NO : SHA4307P  
 MILEAGE : 0000000000  
 MAKE : HYUNDAI  
 MODEL : IONIQ(G3)  
 DATE OF REGN : 25.10.2019  
 DATE/TIME IN : 15.08.2022 11:00  
 ACCIDENT DATE : 07.08.2022

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

0001	04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52
0002	04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00
0003	04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60
0004	04-01-0104-1150-A	PROTECTOR MAT	1 N	50.00	2.00-	50.00
0005	04-01-0104-0851-G	REFLECTOR/REFLEX ASSY-RR	1	41.45	20.00	33.16

SUB-TOTAL : 829.28

## JOB NATURE

0000	L	PANEL BEAT (SHA4307P)TP				350.00
0001	SP	SPRAYPAINT CHARGE				250.00
0002	L	REMOVE/REFIX REVERSE SENSOR				40.00
0003	L	MERIMEN FEE			11.00	

SUB-TOTAL : 651.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305526418  
REGN NO : SHA4307P  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : IONIQ(G3)  
DATE OF REGN : 25.10.2019  
DATE/TIME IN : 15.08.2022 11:0  
ACCIDENT DATE : 07.08.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 1,480.28

MVA NAME & SIGNATURE  
DATE :



AUTHORISED : YES / NO  
SURVEYOR NAME & SIGNATURE  
DATE :