

**ComfortDelGro Engineering Pte Ltd** (Co.Reg.No:199506048W)59 Loyang Drive  
Singapore 508969  
Tel: 6214 8300**TP INSURER:**  
**CTPL****India International Insurance Pte Ltd (HQ)***Jumani  
CTPL*

Singapore

**PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	07/08/2022
Vehicle Reg. No.:	<b>SHA4307P</b>	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI AE IONIQ, 1.6 (A)	Vehicle Reg. Date:	25/10/2019
Vehicle Colour:	BLUE	Chassis No:	KMHC851CVLU187151
Engine No:	G4LEKU399654		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	<b>NO</b>		
Est. Duration of Repair (day)	4		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

<b>COST OF CLAIMS</b>	<b>Amount</b>
Parts	1,189.76
Miscellaneous Items	11.00
Labour	750.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>1,950.76</b>
<b>+ GST 7.00% (S\$)</b>	<b>136.55</b>
<b>Nett Amount (S\$)</b>	<b>2,087.31</b>

**This claim is handled by: JUMANI BIN MASUDIN**

Generated using Merimen e-Claims Internet Estimation &amp; Adjusting System

**REPAIR DETAILS**

**Reference**

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 15 Aug 2022)  
**Parts:** 143      HYUNDAI AE IONIQ 1.6 (A) (Catalogue:Merimen Singapore 1.0)  
**Labour:** Repairer's      (Price-denominated Standard List)  
**Print Code:** **ComfortDelGro Engineering Pte Ltd/SHA4307P/15/08/2022 14:08**  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER ASSY / <i>Re</i>	20.00	0.00	*459.40 FL
2	10		*REAR BUMPER CLIPS / <i>REC</i>	20.00	0.00	*22.00 FL
3	1		*REAR BUMPER BEAM / <i>NN</i>	20.00	0.00	*394.80 FL
4	1		*REAR BUMPER CENTRE MOULDING / <del>XXXX</del> / <i>Cut</i>	20.00	0.00	*451.25 FL
5	1		*REFLECTOR LH / <i>Cut</i>	20.00	0.00	*41.45 FL
6	1		*REAR BUMPER BRACKET LH	20.00	0.00	*55.80 FL
7	1		*REAR BUMPER MAT / <i>ML</i>	0.00	0.00	*50.00 F
<b>Sub Total (\$\$)</b>						<b>1,474.70</b>
<b>- List Item Discount on L Items (\$\$)</b>						<b>284.94</b>
<b>Total Parts (\$\$)</b>						<b>1,189.76</b>

F=Franchise part. L=ListItemDisc.

**ComfortDelGro Engineering Pte Ltd/SHA4307P/15/08/2022 14:08.** Not valid without Reference section.  
 Generated using **Merimen e-Claims IEAS**

# Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<b>Miscellaneous Items</b>			11.00
1	1	OD/TP Case (Insurer)	
<b>Sub Total (\$)</b>			<b>11.00</b>

# Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	PANEL BEATING	New	350 400.00
2	SPRAYPAINT	New	250 300.00
3	REMOVE/REFIX REVERSE SENSOR	New	40 50.00
<b>Gross Labour Cost (\$)</b>			<b>750.00</b>

ComfortDelGro Engineering Pte Ltd/SHA4307P/15/08/2022 14:08. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

2 Days.  
P/P  
Gino Qof  
16/8/22  
4/pm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts price to be confirmed to confirmation
- Third party liability on a "without Prejudice" basis
- No ill feeling to be allowed
- Supplier to be notified and approved and is subject to the approval of the Insurance Company

Acknowledged by Repairer  
Signature:  
Date: