



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile          |                                                                                                                    |                 |                                                         |         |
|----------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------|-----------------|---------------------------------------------------------|---------|
| HL ASSURANCE PTE LTD<br>11 KEPPEL ROAD<br>#11-01 ABI PLAZASINGAPORE 089057 |                                                                                                                    |                 | Ref: CS/HLA22007881/y3<br>Date: 17/08/2022<br>Code: HLA |         |
| <b>1. Policy Particulars :- OWN DAMAGE</b>                                 |                                                                                                                    |                 |                                                         |         |
|                                                                            | Insured Veh.                                                                                                       | Veh. Inspected  | SJJ 2606T                                               |         |
|                                                                            | Policy No. MP315524                                                                                                | Coverage (\$)   | 0.00                                                    |         |
|                                                                            | Claim No. MPC03596/WF                                                                                              | Excess (\$)     | 775.00                                                  |         |
|                                                                            | Assign From WONG WEE FU                                                                                            | Assign Date     | 17/08/2022                                              |         |
| <b>2. Vehicle Particulars &amp; Condition</b>                              |                                                                                                                    |                 |                                                         |         |
|                                                                            | Make & Model                                                                                                       | c.c             | 0                                                       |         |
|                                                                            | Engine No. HIDDEN                                                                                                  | Year of Reg.    |                                                         |         |
|                                                                            | Chassis No.                                                                                                        | Colour          |                                                         |         |
|                                                                            | Odometer -                                                                                                         | Steering        |                                                         |         |
|                                                                            | Brakes                                                                                                             | Modification    |                                                         |         |
|                                                                            | General                                                                                                            |                 |                                                         |         |
| <b>3. Conditions of Tyres</b>                                              |                                                                                                                    |                 |                                                         |         |
|                                                                            |                                                                                                                    | Size            | Make                                                    | Balance |
|                                                                            | R/H Front Tyre                                                                                                     |                 |                                                         | mm      |
|                                                                            | L/H Front Tyre                                                                                                     |                 |                                                         | mm      |
|                                                                            | R/H Rear Tyre                                                                                                      |                 |                                                         | mm      |
|                                                                            | L/H Rear Tyre                                                                                                      |                 |                                                         | mm      |
| <b>4. Description of Damages</b>                                           |                                                                                                                    |                 |                                                         |         |
|                                                                            |                                                                                                                    |                 |                                                         |         |
| <b>5. General Information</b>                                              |                                                                                                                    |                 |                                                         |         |
|                                                                            | Accident Date 08/08/2022                                                                                           | Inspection Date |                                                         |         |
|                                                                            | Survey held at COMFORTDELGRO ENGINEERING PTE LTD<br>205 BRADDELL ROAD<br>BLK C, 3RD FLOOR<br>SINGAPORE 579701.     |                 |                                                         |         |
| <b>5a. Remarks</b>                                                         |                                                                                                                    |                 |                                                         |         |
|                                                                            | A)THE MARKET VALUE IS S\$------(EST. AVERAGE)<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS. |                 |                                                         |         |