

m: 98448533 t: 63855510 w: www.detaillab.com.sg

PREMIER@Kaki Bukit, 8 Kaki Bukit Ave 4, #02-03/04 S415875

LONPAC INSURANCE BHD

REQUEST FOR PRE-REPAIR SURVEY

CAR PLATE: SGK3105X

CAR: MAZDA3

OWNER'S NAME: LEONG MAY LIAN

We are authorised by the owner MS LEONG MAY LIAN to assist her to claim Third Party against YN5995B (Your Insured) to her vehicle as a result of an accident.

We append our estimates for the repairs upon appointed surveyor on-site at our workshop.

Please acknowledge and advise us on PRS date/time applicable under your insured policy.

Please also arrange for the survey to be arranged as soon as possible.

Vehicle number: YN5995B (YOUR INSURED)

Policy Number: NA

Date & Time of Accident: 16/08/2022 0825HRS

Location: NEAR DELTA ROAD

DATE: 17/08/2022 DETAIL LAB Ben Yap Authorised Manage

Authorised Manager mobile: 9844 8533

