

08/11/21 waf

ASS. BY: Ram

REF:

CS3/AW 22007898/RVY3

199

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SNB 5990H

at Workshop n/s ONE-ZONE AUTOMOTIVE

of 1016 MUSHAM Ind Pk A

Insured SKW 5925Y AB

Policy No. _____

Claims No. 2022 22006088JK

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

| | |
|-----|-----|
| N/S | O/S |
| | |

Bal. or Market Value: 94K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lim Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SNB 5990H Yr Regn: 2016, CG

Type: (M) Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: VOLVO XC60TS c.c. 1969

Colour: Brown A/C: Insured / Std / NI / NA

Sp. Reading: 78012 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: YNP240LDH2041844

Gen. Cond: (G) Good / Fair / Poor / Burnt

Steering: (I) Inorder / Jammed / Leaked / Burnt or

Brake: (I) Inorder / Jammed / Leaked / Burnt or

Modi: (S) Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R20

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / (P) PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. 05/08/22 D.O.L. 18/08/22

Survey held at

ONE-ZONE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 4TK

22/8/22

ESTIMATE RANGE OF REPAIR / NO. OF DAYS - (2K-4K) / 3 days

Date/Time, File Pass to?

Prell Report

1)

Final Report

Date/Time, File Return to?

2) 22/8/22-typist

Days Of Repair: 3

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Report Format : _____

Lump Sum / I.B.I. (\$) _____

Add Fee:

Site Insp (\$ _____)

Interview (\$ _____)

Tech. Invs (\$ _____)

Weekend (\$ _____)

| |
|--|
| |
| |
| |
| |
| |

Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars | |
|-------------------------------------|---------------------------------------|
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 179F |
| Vehicle Details | |
| Vehicle No.: | SNB5990H |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 21 Aug 2022 |
| Vehicle Make: | VOLVO |
| Vehicle Model: | XC60 T5 |
| Primary Colour: | Brown |
| Manufacturing Year: | 2016 |
| Engine No.: | B4204T111734018 |
| Chassis No.: | YV1DZ40LDH2041844 |
| Maximum Power Output: | 180.0 kW (241 bhp) |
| Open Market Value: | \$36,151.00 |
| Original Registration Date: | 17 Oct 2016 |
| First Registration Date: | 17 Oct 2016 |
| Transfer Count: | 1 |
| Actual ARF Paid: | \$42,612.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 16 Oct 2026 |
| PARF Rebate Amount: | \$29,828.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 16 Oct 2026 |
| COE Category: | B - Car above 1600cc or 97kW (130bhp) |
| COE Period(Years): | 10 |
| QP Paid: | \$55,501.00 |
| COE Rebate Amount: | \$23,040.00 |
| Total Rebate Amount: | \$52,868.00 |

The information contained herein is correct as at 21 Aug 2022

OK

Volvo XC60 T5 2.0A

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price

\$85,800

Depreciation 

\$17,780 /yr

[View models with similar depre](#)

Reg Date

26-Apr-2016

(3yrs 8mths 4days COE left)

Mileage

69,000 km (10.9k /yr)

Manufactured 

2015

Road Tax 

\$1,176 /yr

Transmission

Auto

Dereg Value 

\$44,766 as of today ([change](#))

OMV 

\$34,851

COE 

\$49,602

ARF 

\$40,792

Engine Cap

1,969 cc

Power

180.0 kW (241 bhp)

Curb Weight 

1,722 kg

No. of Owners 

2

Type of Vehicle

SUV